

(08/11/13) wef

ASS. REF. BY: Marcus

REF:

CS/SMA 200/1785/UVF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 93 E 1748U

at Workshop m/s 72C 10a

of _____

Insured: SKC 7165R

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$32

IDAC Accident Rpt: _____ Consistent? : Yes or No

G/A / PR Seen ☒ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

2482

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 6BE 1748U Yr Regn: 9, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM /

Make: Nissan cabstar c.c. 2953

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 221411 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC2F2420857432

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 195-R15 OHTSU

R: 165 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. 6 mm

R/Bal. 6/6 mm

L/Bal. 6 mm

L/Bal. 8/6 mm

D.O.A. 27/10/20

D.O.I. 30/10/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have G.A

LTA # 19649 To: Joke 1399.70N

5/11/20 confirmed Lump Sum \$3900 with AH che; (Red 7253.94, 65%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 6/11/20-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

___ S + RS, ___ SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / t.B.: (\$ 3900)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

ESTIMATE

- LKK to consult the repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

T & C Automotive
1 Kaki Bukit Avenue 6
#01-68
Singapore 417883

Vehicle No.: GBE7148U
 Make/Model: Nissan Cabstar

Acknowledged by Repairer

not Authorized
 1/5 3900
 30/10/20
 the phs After repair
 4 days.

Descriptions	Qty	Unit Price	Amount
Spare Parts			
Tail gate <i>bully 20</i>	1	\$1,688.40	\$1,688.40
Tail gate lower lock RH <i>su</i>	1	\$183.20	\$183.20
Tail gate lower lock LH <i>su</i>	1	\$183.20	\$183.20
Rear end panel <i>R</i>	1	\$884.10	\$884.10
Rear floor member <i>R</i>	1	repair	repair
Rear chassis LH <i>R</i>	1	repair	repair
			\$2,938.90
		Less 30%	\$881.67
		Sub Total 1	\$2,057.23
Nett			
Tail gate "Nissan" sticker <i>su</i>	1	\$125.90	\$125.90
Tail lamp RH <i>su</i>	1	\$297.20	\$297.20
Tail lamp LH <i>208-20 su</i>	1	\$297.20	\$297.20
Tail lamp bracket RH <i>NS</i>	1	\$197.70	\$197.70
Tail lamp bracket LH <i>NS</i>	1	\$197.70	\$197.70
Tail gate stopper <i>70cm</i>	4	\$15.90	\$63.60
Tail gate stopper bracket RH <i>Beal</i>	1	\$177.50	\$177.50
Tail gate stopper bracket LH <i>R</i>	1	\$177.50	\$177.50
Spare tyre bracket <i>bully 20</i>	1	\$378.50	\$378.50
Spare tyre retainer <i>> complete one</i>	1		\$164.00
Rear <i>buzzle</i>	1		\$175.10
Rear number plate holder bracket <i>148-20 su</i>	1	\$175.10	\$175.10
			\$2,251.90
		Less 10%	\$225.19
		Sub Total 2	\$2,026.71
Special Nett			
Reverse sensor (set) <i>one</i>	1 set	\$270.00	\$270.00
Rear under run bumper <i>sent</i>	1	\$650.00	\$650.00
Tail gate aluminium plate w/rivet <i>su</i>	1	\$900.00	\$900.00
Rear floor member aluminium plate w/rivet <i>11</i>	1	\$1,400.00	\$1,400.00
70km/h sticker <i>su</i>	1	\$15.00	\$15.00
13pax sticker <i>su</i>	1	\$15.00	\$15.00
Spare tyre - rear <i>su</i>	1	\$350.00	\$350.00
Spare tyre - front <i>su</i>	1	\$450.00	\$450.00
		Sub-Total 3	\$4,050.00
Labour			
Rewiring.			\$80.00
Panel beating charges to remove & replace, to cut & weld, to knock & reshape damaged parts and areas.			\$1,400.00
Putty and spray painting affected areas.			\$1,200.00
Anti-rust undercoating.			\$120.00
To realign canopy.			\$220.00
		Labour	\$3,020.00
		Total Repair Cost	\$11,153.94

L - 1688.40
 302
 1181.88

N - 1230.9
 107
 1107.81

S - 870
 L - 1720
 4879.69
 3903