



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20011785/Uvf3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 09-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 7165R	Veh. Inspected	GBE 1748U
Policy No.	D20MTRENT000453	Coverage (\$)	0.00
Claim No.	CMTD2003144/MYE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	29/10/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR (M)	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1SC2F24Z0857432	Colour	SILVER
Odometer	221411	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	165 R13 (D)	FALKEN	6/6 mm
L/H Rear Tyre	165 R13 (D)	FALKEN	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/10/2020	Inspection Date	30/10/2020
Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------