

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WONG BAN KENG
BLK 78 DAWSON RD #24-57
SINGAPORE 141078

Contact : 98576377

ESTIMATE

Repair Code : CLM15070

Date in : 24/10/2020

Vehicle Num. : SLR9P

Model : TOYOTA ALPHARD 2.5 CVT ELEGANCE S/R

Chassis/Eng# : JTNGF3DHX08003340/2ARH660989

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	2078.70	2078.70 1850
FRONT RH DOOR FRAME BLACK STICKER (NO:1) <i>2 new</i>	1	21.90	21.90
FRONT RH DOOR FRAME BLACK STICKER (NO:2) <i>2 new</i>	1	39.30	39.30
FRONT RH DOOR GUIDE RUBBER STOPPER <i>new</i>	2	5.50	11.00
FRONT RH DOOR INNER PLASTIC SEAL COVER <i>2 new</i>	1	60.40	60.40
FRONT RH DOOR LOWER WEATHER STRIP SEAL <i>1959-90</i>	1	50.50	50.50
FRONT RH DOOR PROTECTOR GARNISH <i>could</i>	1	812.10	812.10 702
FRONT RH DOOR VERTICAL GARNISH <i>new</i>	1	103.40	103.40
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	205.20	205.20
Subtotal before discount			3,382.50
Percentage discount 25%			845.63
Sub-total 1			2,536.88
FRONT RH DOOR INNER TRIM BOARD CLIP - SET <i>new</i>	1	50.00	50.00
Subtotal before discount			50.00
Percentage discount 0%			0.00
Sub-total 2			50.00
Parts-total			2,586.88

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

WONG BAN KENG

BLK 78 DAWSON RD #24-57

SINGAPORE 141078

Contact : 98576377

ESTIMATE

Repair Code : CLM15070

Date in : 24/10/2020

Vehicle Num. : SLR9P

Model : TOYOTA ALPHARD 2.5 CVT ELEGANCE S/R

Chassis/Eng# : JTNGF3DHX08003340/2ARH660989

LABOUR

To reset system after repair works

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

100
~~200.00~~

80 ~~100.00~~

350 ~~650.00~~

200 ~~400.00~~

~~50.00~~

1,400.00

3,986.88

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Li
P/P 03/11/20.

03 days ✓

total 2689.90 ✓

(P/P)

2689.90 ✓