

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20011796/REA3Q2**Date:** 08/06/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SJY9484C	Insured Vehicle No :	SHC3342H
Date of Loss:	26/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100458

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY9484C	Engine No:	CDN139962
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZ8K5BA023596
Reg. Date:	15/10/2010 (Man. Year: 2010)	Odometer:	106152 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,099.55	0.00	3,099.55	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	750.00	560.00	42.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,409.55	750.00	3,659.55	82.99
+ GST 7.00/7.00% (S\$)	308.67	52.50	256.17	82.99
Nett Amount (S\$)	4,718.22	802.50	3,915.72	82.99
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	29/10/2020	
Date Inspected:	05/11/2020	Inspected At: VAG Singapore Pte Ltd (HQ) 48 Toh Guan Road East, #05-155 Enterprise Hub Singapore 608586
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2022)
Parts:	143	AUDI A4 2.0 TFSI QU S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY9484C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,418.00 FL	*- FL
2	1		*FRONT GRILLE	Not Necessary	459.00 FL	*- FL
3	1		*BONNET	Repair	1,312.00 FL	*- FL
4	1		*SUNDRIES	Not Necessary	35.00 FS	*- FS
5	1		*FRONT LICENCE PLATE	Not Necessary	35.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					3,259.00	0.00
- List Item Discount on L Items 5.00/5.00% (\$\$)					159.45	0.00
Total Parts (\$\$)					3,099.55	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT FRONT BUMPER,GRILLE,BONNET,LICENCE PLATE AND OTHER ASSOCIATED COMPONENTS	New	560.00	250.00
2	SURFACE PREPARATION,SPRAY PAINT AND POLISH FRONT BUMPER,BONNET AND OTHER AFFECTED AREAS	New	750.00	500.00
Gross Labour Cost (\$\$)			1,310.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >