

Repair Estimate

VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Date : 27-Oct-2020

Vehicle Num : SJY9484C

Make/Model : AUDI A4 2.0 TFSI QU

Chassis No : WAUZZZ8K5BA023596

S/N	PARTS	QTY	PRICE	TOTAL
1	Front Bumper <i>repair</i>	1	\$ 1,418.00	\$ 1,418.00
2	Front Grille ?	1	\$ 459.00	\$ 459.00
3	Bonnet <i>repair</i>	1	\$ 1,312.00	\$ 1,312.00
<i>Repair</i> <i>Up 9001008</i> <i>3 days</i> <i>4/5</i> <i>05/11/2020 @ 1345</i> <i>Res after repair</i>				
TOTAL PARTS				\$ 3,189.00
Less 5%				\$ 159.45
TOTAL AMOUNT				\$ 3,029.55
MISCELLANEOUS ITEM				
1	Sunderies		\$ 35.00	\$ 35.00
2	Front Licence Plate		\$ 35.00	\$ 35.00
LABOUR				
1	Remove and refit Front Bumper, Grille, Bonnet, Licence Plate and other associated components.		\$ 560.00	\$ 560.00 <i>250</i>
2	Surface preparation, spray paint and polish Front Bumper, Bonnet and other affected areas.		\$ 750.00	\$ 750.00 <i>500</i>
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
TOTAL				\$ 4,409.55
GST 7%				\$ 308.67
GRAND TOTAL				\$ 4,718.22
Acknowledged by Repairer				

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: