

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 92327457

TO	: AIG	DATE	: 29/10/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SKE2537Z		Xvonne
VEHICLE MODEL	: MERCEDES BENZ C180 COUPE		XiaoChun
CHASSIS NO	: WDD2043492F831548		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XIAN / 92327457	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT RH FENDER <i>Dented</i>	1	\$ 925.00	\$ 925.00
2	FRONT RH FENDER INNER SHIELD <i>ut</i>	1	\$ 198.00	\$ 198.00
3	FRONT RH FENDER CHROME MOULDING <i>3 new</i>	1	\$ 45.00	\$ 45.00
4	FRONT RH FENDER BLUE EFFICIENCY EMBLEM	1	\$ 55.00	\$ 55.00
5	FRONT RH DOOR <i>Dented</i>	1	\$ 2,739.00	\$ 2,739.00
6	FRONT RH DOOR LOCK <i>new</i>	1	\$ 448.00	\$ 448.00
7	FRONT RH DOOR WEATHERSTRIPE <i>New</i>	1	\$ 289.00	\$ 289.00
8	FRONT RH DOOR HINGE <i>3 new</i>	2	\$ 110.00	\$ 220.00
9	FRONT RH DOOR CHECK <i>new</i>	1	\$ 95.00	\$ 95.00
10	FRONT RH DOOR LOWER CHROME MOULDING <i>new</i>	1	\$ 128.00	\$ 128.00
11	FRONT RH DOOR INNER TRIM BOARD <i>new</i>	1	\$ 1,158.00	\$ 1,158.00
12	FRONT RH WHEEL RIM <i>ut</i>	1	\$ 1,250.00	\$ 1,250.00
13	FRONT RH LOWER ARM <i>Bent</i>	1	\$ 295.00	\$ 295.00
14	FRONT RH CONTROL ARM <i>Bent</i>	1	\$ 245.00	\$ 245.00
15	FRONT RH KNUCKLE ARM <i>Dnc</i>	1	\$ 674.00	\$ 674.00
16	FRONT RH WHEEL HUB C/W BEARING <i>Dnc</i>	1	\$ 395.00	\$ 395.00
17	FRONT RH SHOCK ABSORBER <i>Bent</i>	1	\$ 647.00	\$ 647.00

TOTAL PRICE: \$ 9,806.00
LESS 10% \$ 980.60
SUB TOTAL PRICE: \$ 8,825.40

5971
537390
SN: 8W

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT RH FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00

2	FRONT RH DOOR INNER TRIM BOARD CLIPS <i>He ru</i>	1 SET	\$ 50.00	\$ 50.00	X
	<i>30</i>	TOTAL :		\$ 80.00	

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 800.00	<i>500</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>600</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO TRANSFER FRONT DOOR FITTINGS	\$ 150.00	<i>80</i>	
5	TO DISMANTLE FRONT UNDERCARRIAGE	\$ 380.00	<i>220</i>	
6	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80</i>	
	TOTAL:	\$ 2,580.00	<i>1510</i>	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 8,905.40

TOTAL LABOUR COST: \$ 2,580.00

TOTAL REPAIR COST: \$ 11,485.40

total: 7713.80

u/s: 6K (Nett Value)

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

06 Days

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: