

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

29 OCT 2020

**E S T I M A T E**

Estimate No. : b1 56391  
Date Estimated : 28/10/2020  
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -  
Balasubramaniam S/O M M Pillay  
Blk 53 Geylang Bahru  
#16-3603

Singapore 330053

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SBU3999P  | WBAJA120X0WW28534 | 29/03/2019 | 520i  | 0       |

| DESCRIPTION                                                                                     | VALUE          |
|-------------------------------------------------------------------------------------------------|----------------|
| Replace rear floor pan, tail pan, rear boot lid rear bumper<br>include remove attachment etc    | 4250 10,200.00 |
| Spray painting both rear side fender, floor pan, rear tail pan<br>rear boot lid and rear bumper | 3015 5,120.00  |
| To replace front centre exhaust silencer including alignment<br>and conduct checks for leak.    | 457 531.00     |
| To replace rear exhaust silencer including alignment system<br>and conduct check for leak.      | 457 531.00     |
| To remove and install boot compartment carpet and garnish to<br>facilitate repair.              | 230 271.00     |
| To check electrical wiring system and lighting at the rear<br>section for proper function.      | 150 177.00     |
| To carry out body cavity preservation. (For cut panel).                                         | 451 531.00     |
| To carry out body cavity preservation. (Per panel).                                             | 100 118.00     |
| To supply rear emboss number plate.                                                             | ? 83.00        |
| Sundries                                                                                        | ? 150.00       |

Total Labour 1: 17,712.00

| DESCRIPTION          | QTY | PRIC     | VALUE      |
|----------------------|-----|----------|------------|
| TRANSMISSION BRACKET | 1   | 58.65    | ? 58.65    |
| CLAMPING BUSH        | 1   | 60.90    | ? 60.90    |
| CLAMPING BUSH        | 1   | 60.90    | ? 60.90    |
| FRT SILENCER         | 1   | 1,432.60 | ? 1,432.60 |
| INTERMEDIATE PIPE    | 1   | 592.05   | ? 592.05   |
| REAR SILENCER        | 1   | 1,346.70 | ? 1,346.70 |

11/11/2020  
Money Sum & repair  
Covers may use better rental first  
Due 9/11/2020

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 56391  
Date Estimated : 28/10/2020  
Prepared By : Chua Kee Sin

Page No. : 2 of 6

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SBU3999P  | WBAJA120X0WW28534 | 29/03/2019 | 520i  | 0       |

| DESCRIPTION                         | QTY | PRIC     | VALUE       |
|-------------------------------------|-----|----------|-------------|
| RR TRUNK FLOOR CROSS MEMBER         | 1   | 120.75   | ? 120.75    |
| COMPLETE TAIL TRIM                  | 1   | 837.80   | ? 837.80    |
| Extension, s                        | 1   | 31.90    | ? 31.90     |
| Extension, s                        | 1   | 31.90    | ? 31.90     |
| REAR LUGGAGE COMPARTMENT FLOOR      | 1   | 279.55   | ? 279.55    |
| LH BRACKET OPENING AID              | 1   | 96.05    | ? 96.05     |
| RH BRACKET OPENING AID              | 1   | 96.05    | ? 96.05     |
| TAILGATE ALUMINIUM                  | 1   | 1,749.70 | bt 1,749.70 |
| LH TRUNK LID HINGE                  | 1   | 119.40   | ? 119.40    |
| RH TRUNK LID HINGE                  | 1   | 119.40   | ? 119.40    |
| OUTER PANEL TAIL TRIM               | 1   | 586.45   | bt 586.45   |
| REAR BUMPER CARRIER                 | 1   | 862.10   | bt 862.10   |
| LEFT PROTECTION FOIL                | 1   | 13.45    | ? 13.45     |
| RIGHT PROTEC                        | 1   | 13.45    | ? 13.45     |
| REAR BUMPER BOTTOM REINFORCEMENT    | 1   | 88.15    | ? 88.15     |
| REAR BUMPER CENTRE GUIDE            | 1   | 67.45    | dis 67.45   |
| REAR BUMPER LH SIDE GUIDE           | 1   | 67.45    | ? 67.45     |
| REAR BUMPER RH SIDE GUIDE           | 1   | 67.45    | ? 67.45     |
| REAR BUMPER TRIM STRIP              | 1   | 105.70   | cr 105.70   |
| REAR BUMPER TOWING EYE FLAP PRIMED  | 1   | 52.60    | mis 52.60   |
| REAR BUMPER PANEL PRIMED (PDC/PMA)  | 1   | 1,619.15 | de 1,619.15 |
| SET MOUNTING PMA SENSOR             | 1   | 69.35    | re 69.35    |
| EMBLEM GROMMET                      | 2   | 0.85     | re 1.70     |
| LETTERING 520i                      | 1   | 64.45    | re 64.45    |
| BREAKTHROUGH BUFFER                 | 2   | 8.75     | ? 17.50     |
| PLAQUE 74MM                         | 1   | 71.60    | re 71.60    |
| LH TENSION SPRING                   | 1   | 76.75    | ? 76.75     |
| BOOT LID/TAILGATE PUSH BOTTON (RFK) | 1   | 38.20    | de 38.20    |
| TRUNK LID POWER LOCK PANEL          | 1   | 241.65   | ? 241.65    |
| COUNTER SUPPORT REAR VIEW CAMERA (R | 1   | 4.70     | ? 4.70      |
| LOCK TRUNK LID                      | 1   | 229.10   | ? 229.10    |
| RH SPINDLE DRIVE                    | 1   | 583.30   | ? 583.30    |
| REAR SILENCER HEAT INSULATION FRT   | 1   | 114.85   | ? 114.85    |
| HEAT INSULATOR FLOOR PANEL TRUNK    | 1   | 37.30    | ? 37.30     |
| WARNING SIGNALLER                   | 1   | 35.35    | ? 35.35     |
| TRUNK LID GASKET                    | 1   | 128.70   | ? 128.70    |
| (S/L) CLIP                          | 2   | 5.45     | ? 10.90     |
| REAR LH REAR REFLECTOR              | 1   | 38.85    | ? 38.85     |
| REAR RH REAR REFLECTOR              | 1   | 38.85    | ? 38.85     |
| REAR LH LIGHT IN THE SIDE PANEL     | 1   | 637.95   | an 637.95   |
| REAR RH LIGHT IN THE SIDE PANEL     | 1   | 637.95   | ? 637.95    |
| REAR LH LIGHT IN TRUNK LID          | 1   | 376.80   | cr 376.80   |
| REAR RH LIGHT IN TRUNK LID          | 1   | 376.80   | ? 376.80    |
| LH TAIL LIGHT FINISHER TRUNK LID    | 1   | 35.15    | an 35.15    |
| RH TAIL LIGHT FINISHER TRUNK LID    | 1   | 30.35    | an 30.35    |
| ULTRASONIC SENSOR BLUESTONE (C2Y)   | 4   | 381.90   | ? 1,527.60  |
| DECOUPING RING PDC TORQUE CONVERTER | 4   | 5.10     | re 20.40    |
| BLIND RIVET AVIBVLB                 | 33  | 0.55     | re 18.15    |
| BLIND RIVET AVIBVLB                 | 46  | 0.55     | re 25.30    |

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 56391  
Date Estimated : 28/10/2020  
Prepared By : Chua Kee Sin

Page No. : 3 of 6

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SBU3999P  | WBAJA120X0WW28534 | 29/03/2019 | 520i  | 0       |

| DESCRIPTION                       | QTY | PRIC   | VALUE  |
|-----------------------------------|-----|--------|--------|
| SCREW (SF PLUS M5X15)             | 4   | 0.55   | 2.20   |
| SCREW (SF PLUS M5X15)             | 4   | 0.55   | 2.20   |
| (DG/SL) BODY ADHESIVE K5B (195ML) | 1   | 331.80 | 331.80 |
| (DG/SL) BODY ADHESIVE K5B (195ML) | 1   | 331.80 | 331.80 |
| (DG) CLEANER R1 (100ML)           | 1   | 26.15  | 26.15  |
| (DG) CLEANER R1 (100ML)           | 1   | 26.15  | 26.15  |
| PUNCH RIVET N4                    | 19  | 0.55   | 10.45  |
| PUNCH RIVET N4                    | 24  | 0.55   | 13.20  |
| (S/L) SEAM SEAL 300ML             | 1   | 33.80  | 33.80  |
| (S/L) SEAM SEAL 300ML             | 1   | 33.80  | 33.80  |

Total Parts : 16,878.80

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date &amp; Time 11/11/20 12pm Excess S\$ \_\_\_\_\_

Surveyor's Name Tanjir Sign [Signature]

Surveyor's Tel 97495449 Authorised Yes / No \_\_\_\_\_

Authorised Date WP Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No \_\_\_\_\_

Surveyor's E-mail tanjir@lkkauto.com

No. of Working Days Recommend 8-9 days



|                |   |           |
|----------------|---|-----------|
| Labour 1       | : | 17,712.00 |
| Parts          | : | 16,878.80 |
| Labour 2       | : | 0.00      |
| Excess         | : | 0.00      |
| Total GST @ 7% | : | 2,421.36  |
| Grand Total    | : | 37,012.16 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*