



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103224

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/05/2021
Reference CC3/CTI20011809/Krs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9970A
Insured Veh. SMP 7650P
Claim No. SNM20D204107/LKKDS
Policy No. DMPCSN3072031900
Accident Date 27/10/2020
Inspection Date 28/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20011809/Krs3q2	
			Date: 10/05/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 7650P	Veh. Inspected	SHD 9970A	
Policy No.	DMPCSN3072031900	Coverage (\$)	0.00	
Claim No.	SNM20D204107/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	28/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTDKB3FU003091526	Colour	M . P. WHITE / RED	
Odometer	15307 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DUNLOP	9 mm	
L/H Front Tyre	195/65 R15	DUNLOP	9 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	9 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2020	Inspection Date	28/10/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9970A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER ,REAR BUMPER	TO REPAIR SEE LABOUR	485.60	-
1	RETAINER ,REAR BUMPER SIDE ,RH	SERVICEABLE	132.60	-
1	PANEL SUB-ASSY ,REAR DOOR ,LH	BENT	1,294.90	1,294.90
1	MOTOR ASSY ,POWER WINDOW REGULATOR ,LH	SERVICEABLE	926.00	-
1	REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	SERVICEABLE	206.70	-
1	MOULDING ASSY ,BODY ROCKER PANEL LH	TO REPAIR SEE LABOUR	594.80	-
1	PANEL SUB-ASSY ,QUARTER LH	BENT	871.50	871.50
1	LINER ,REAR WHEEL HOUSE ,LH	SERVICEABLE	139.80	-
1	TAPE ,BLACK OUT ,NO.1 REAR LH	NECESSARY	21.90	21.90
1	TAPE ,BLACK OUT ,NO.2 REAR LH	NECESSARY	34.90	34.90
1	TAPE ,BLACK OUT ,NO.3 REAR LH	NECESSARY	15.40	15.40
	LESS 10% DISCOUNT		-472.41	-
	LESS 25% DISCOUNT		-	-559.65
			4,251.69	1,678.95
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	75.00	-
1	SET BUMPER RETAINER CLIP RR (SN)	NOT NECESSARY	65.00	-
1	SET REAR DOOR STICKER 65553333 (SN)	NECESSARY	100.00	60.00
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
1	TYRE (SN)	SERVICEABLE	300.00	-
1	TYRE RIM (SN)	SERVICEABLE	350.00	-
1	TYRE RIM COVER (SN)	TO REPAIR SEE LABOUR	200.00	-
			1,970.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF COVER ,REAR BUMPER ,MOULDING ASSY ,BODY ROCKER PANEL LH AND TYRE RIM COVER .		1,600.00	800.00
	TO REMOVE AND REFIT REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,600.00	800.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	100.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			4,560.00	1,780.00
	GRAND TOTAL		10,781.69	3,518.95
RECOMMENDED COST OF REPAIRS				3,518.95

Report Ref No. CC3/CTI20011809/Krs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 9970A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

