

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9970A****AAD2010-121***Not Authored**Repair B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**20 OCT 2020****SHD9970A**

JTDKB3FU003091526

TOYOTA

PRIUS GEN 4

27/10/2020

**CHINA**

24/09/2020

	<b>PART</b>
1	COVER, REAR BUMPER
1	RETAINER, REAR BUMPER SIDE, RH
1	PANEL SUB-ASSY, REAR DOOR, LH
1	MOTOR ASSY, POWER WINDOW REGULATOR, LH
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH
1	MOULDING ASSY, BODY ROCKER PANEL, LH
1	PANEL SUB-ASSY, QUARTER, LH
1	LINER, REAR WHEEL HOUSE, LH
1	TAPE, BLACK OUT, NO.1 REAR LH
1	TAPE, BLACK OUT, NO.2 REAR LH
1	TAPE, BLACK OUT, NO.3 REAR LH

	<b>LIST</b>
\$	R 485.60 X
\$	R 132.60 X
\$	R 1,294.90 ✓
\$	926.00 ?
\$	206.70 ?
\$	R 594.80 X
\$	R 871.50 ✓
\$	R 139.80 X
\$	R 21.90 —
\$	R 34.90 —
\$	R 15.40 ✓
<b>TOTAL</b>	<b>\$ 4,724.10</b>
<b>10%</b>	<b>\$ 472.41</b>
	<b>\$ 4,251.69</b>

**Special Nett**

1SET	PARKING AID
1SET	REAR BUMPER CLIP
1SET	BUMPER RETAINER CLIP RR
1SET	REAR DOOR STICKER 65553333
1	Rear Bumper Protector
1	TYRE
1	TYRE RIM
1	TYRE RIM COVER

\$	R 700.00 X
\$	R 75.00 X
\$	R 65.00 X
\$	R 100.00 <i>6050</i>
\$	R 180.00 X
\$	R 300.00 X
\$	R 350.00 X
\$	R 200.00 X
<b>TOTAL</b>	<b>\$ 1,970.00</b>

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9970A

AAD2010-121

<b>TOTAL PARTS</b>	<b>\$</b>	<b>6,221.69</b>
--------------------	-----------	-----------------

**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	1,600.00	<i>Pool</i>
----	----------	-------------

To remove and refit rear bumper fittings, attachment and perform water seepage test.

\$	<i>nn</i> 170.00	<i>X</i>
----	------------------	----------

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	250.00	<i>Pool</i>
----	--------	-------------

Putty And Spray Painting Of The Affected Portion.

\$	1,600.00	<i>Pool</i>
----	----------	-------------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	<i>Pool</i>
----	--------	-------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>Pool</i>
----	--------	-------------

To reinstall rear bumper parking sensor.

\$	<i>nn</i> 170.00	<i>X</i>
----	------------------	----------

To check steering geometry and computer wheel alignment

\$	<i>nn</i> 220.00	<i>X</i>
----	------------------	----------

<b>TOTAL</b>	<b>\$</b>	<b>4,560.00</b>
--------------	-----------	-----------------

<b>Over All Total</b>	<b>\$</b>	<b>10,781.69</b>
-----------------------	-----------	------------------

**(LUMP SUM) Repair Days****20 DAYS***5 days***For Official Use**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: