

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9970A**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

20 OCT 2020

**PART**

- 1 COVER, REAR BUMPER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 PANEL SUB-ASSY, REAR DOOR, LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, LH
- 1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 TAPE, BLACK OUT, NO.1 REAR LH
- 1 TAPE, BLACK OUT, NO.2 REAR LH
- 1 TAPE, BLACK OUT, NO.3 REAR LH

**Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER RETAINER CLIP RR
- 1SET REAR DOOR STICKER 65553333

- 1 Rear Bumper Protector
- 1 TYRE
- 1 TYRE RIM
- 1 TYRE RIM COVER

**AAD2010-121***Not Authored**Penalty B4 paint**8 3518.95***SHD9970A**

JTDKB3FU003091526

TOYOTA

PRIUS GEN 4

27/10/2020

**CHINA**

24/09/2020

**LIST**

|              |           |                 |   |
|--------------|-----------|-----------------|---|
| \$           | <i>12</i> | 485.60          | X |
| \$           | <i>12</i> | 132.60          | X |
| \$           | <i>B3</i> | 1,294.90        | ✓ |
| \$           | <i>12</i> | 926.00          | X |
| \$           | <i>12</i> | 206.70          | X |
| \$           | <i>12</i> | 594.80          | X |
| \$           | <i>B3</i> | 871.50          | ✓ |
| \$           | <i>12</i> | 139.80          | X |
| \$           | <i>12</i> | 21.90           | — |
| \$           | <i>12</i> | 34.90           | — |
| \$           | <i>12</i> | 15.40           | ✓ |
| <b>TOTAL</b> | <b>\$</b> | <b>4,724.10</b> |   |
| <b>10%</b>   | <b>\$</b> | <b>472.41</b>   |   |
|              | <b>\$</b> | <b>4,251.69</b> |   |

|              |           |                 |               |
|--------------|-----------|-----------------|---------------|
| \$           | <i>12</i> | 700.00          | X             |
| \$           | <i>12</i> | 75.00           | X             |
| \$           | <i>12</i> | 65.00           | X             |
| \$           | <i>12</i> | 100.00          | <i>605.00</i> |
| \$           | <i>12</i> | 180.00          | X             |
| \$           | <i>12</i> | 300.00          | X             |
| \$           | <i>12</i> | 350.00          | X             |
| \$           | <i>12</i> | 200.00          | X             |
| <b>TOTAL</b> | <b>\$</b> | <b>1,970.00</b> |               |

**Trans-cab Auto Services Pte Ltd**

AAD2010-121

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9970A

|                    |           |                 |
|--------------------|-----------|-----------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>6,221.69</b> |
|--------------------|-----------|-----------------|

**LABOUR**

|                                                                                                                           |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|------|
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 1,600.00 | 800/ |
| To remove and refit rear bumper fittings, attachment and perform water seepage test.                                      | \$ | 170.00   | nn X |
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                                               | \$ | 250.00   | 60/  |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 1,600.00 | 800/ |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00   | 100/ |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00   | 20/  |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 170.00   | nn X |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00   | nn X |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>4,560.00</b> |
|--------------|-----------|-----------------|

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>Over All Total</b> | <b>\$</b> | <b>10,781.69</b> |
|-----------------------|-----------|------------------|

**(LUMP SUM) Repair Days****20 DAYS****5 days****For Official Use**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: