

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT1200180/unf3

**ASSIGNMENT**

From:

Date:

Veh No:

SGY 6189K

Yr Regn:

10, 07

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

CAI

To Inspect Vehicle No:

SGY 6189K

Make:

Toyota wish

c.c

1794

at Workshop m/s

hockend

Colour

silver

A/C: Insured / Std / NI / NA

of

Sp. Reading

343608

T/Radio: Insured / Std / NI / NA

Insured:

GBE 3769X

Eng/No:

Policy No.

C/No:

ZNE 10 0380666

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F:

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

nexen

Bal. or Market Value:

14

Front

6

Rear

6

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

4  
20

days

Res.: Yes or No

D.O.A.

28/10/20

D.O.I.

9/11/20

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

coe 31-8-2022 L7A89221

reoff 4779

13/11/20 1/5 & 3200 confirmed w. a Anys-s (Red 3247.56, 50%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 13/11/20-Typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format : Merimen

Lump Sum /4.B.1: (\$ 3200

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E

BEDOK NORTH AVE 4,

#01-2008/10/12 SINGAPORE 489977

TEL : 6441 5655 FAX : 6441 5355/6243 8121

R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX070Z

WONG YEW KAY

NO 817 TAMPINES STREET 81

#12-584 TAMPINES POLYVIEW

SINGAPORE 520817

TEL : FAX :

PH : 97360843

ATTN :

## ESTIMATE BILL

Number : EB00005559

Date : 29/10/2020

Case No : AD00011389

Vehicle No : SGY6189K

Chassis : ZNE100380666

Year of Mfr 2007

Policy No 5116820775

Model : TOYOTA WISH 1.8 A

Term:

| Sn                                           | DESCRIPTION                              | QTY | U PRICE  | DISC | AMOUNT   |
|----------------------------------------------|------------------------------------------|-----|----------|------|----------|
| 1                                            | TAILGATE <i>32300</i>                    | 1.0 | 1,272.40 | 25   | 954.30   |
| 2                                            | TAILGATE DAMPER LH <i>229</i>            | 1.0 | 224.63   | 25   | 168.47   |
| 3                                            | TAILGATE DAMPER RH <i>229</i>            | 1.0 | 224.63   | 25   | 168.47   |
| 4                                            | TAILGATE EMBLEM <i>229</i>               | 1.0 | 76.80    | 25   | 57.60    |
| 5                                            | TAILGATE OUTER HANDLE <i>229/160</i>     | 1.0 | 99.25    | 25   | 74.44    |
| 6                                            | TAILGATE INNER LOCK <i>229/160</i>       | 1.0 | 470.40   | 25   | 352.80   |
| 7                                            | TAILGATE WIPER MOTOR <i>229</i>          | 1.0 | 699.60   | 25   | 524.70   |
| 8                                            | REAR NUMBER PLATE LAMP SET <i>229</i>    | 1.0 |          | 25   |          |
| 9                                            | END PANEL <i>32300</i>                   | 1.0 | 468.50   | 25   | 351.38   |
| 10                                           | REAR BUMPER <i>229</i>                   | 1.0 | 550.30   | 25   | 412.73   |
| 11                                           | REAR BUMPER RETAINER RH <i>229</i>       | 1.0 | 55.60    | 25   | 41.70    |
| 12                                           | REAR BUMPER RETAINER LH <i>229</i>       | 1.0 | 55.60    | 25   | 41.70    |
| 13                                           | REAR BUMPER REFLECTOR RH <i>229</i>      | 1.0 | 57.60    | 25   | 43.20    |
| 14                                           | REAR BUMPER REFLECTOR LH <i>229</i>      | 1.0 | 57.60    | 25   | 43.20    |
| 15                                           | REAR BUMPER CLIP <i>229</i>              | 2.0 | 4.50     | 25   | 6.75     |
| 16                                           | REAR BUMPER BRACKET LH <i>229</i>        | 1.0 | 55.60    | 25   | 41.70    |
| 17                                           | TAILAMP LH <i>229</i>                    | 1.0 | 390.54   | 25   | 292.91   |
| 18                                           | REAR FENDER INNER SHIELD LH <i>229</i>   | 1.0 | 259.90   | 25   | 194.93   |
| List Price - Parts Sub Total                 |                                          |     |          |      | 3,770.98 |
| 19                                           | WINDSCREEN SEALANT <i>229</i>            | 2.0 | 24.00    | 0    | 48.00    |
| 20                                           | REAR NUMBER PLATE <i>229</i>             | 1.0 | 30.00    | 0    | 30.00    |
| 21                                           | REAR NUMBER PLATE HOLDER <i>229</i>      | 1.0 | 30.00    | 0    | 30.00    |
| 22                                           | REAR FENDER LH - REPAIR <i>229</i>       | 1.0 |          |      |          |
| Special Nett Price - Parts Sub Total         |                                          |     |          |      | 108.00   |
| Parts Total                                  |                                          |     |          |      | 3,878.98 |
| 23                                           | LABOUR TO REMOVE & REFIT NECESSARY PARTS | 1.0 | 900.00   | 0    | 900.00   |
| 24                                           | SPRAY PAINT ON THE AFFECTED AREAS        | 1.0 | 1,100.00 | 0    | 1,100.00 |
| 25                                           | ANTI-RUST COATING                        | 1.0 | 200.00   | 0    | 200.00   |
| 26                                           | WIRING                                   | 1.0 | 40.00    | 0    | 40.00    |
| 27                                           | TO REMOVE & REFIT WINDSCREEN             | 1.0 | 180.00   | 0    | 180.00   |
| Labour 1 Sub Total                           |                                          |     |          |      | 2,420.00 |
| <i>Rear end panel top garnish 198.10 7m1</i> |                                          |     |          |      |          |

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

\* N = Item not subjected to GST

Page 1 of 2

LKK Auto Consultants hence notify

of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and approved by LKK Auto Consultants

Acknowledged by Repairer

Signature:

Issued by : Anysia

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXXX070Z  
WONG YEW KAY  
NO 817 TAMPINES STREET 81  
#12-584 TAMPINES POLYVIEW  
SINGAPORE 520817  
TEL : FAX :  
PH : 97360843  
ATTN :

## ESTIMATE BILL

Number : EB00005559  
Date : 29/10/2020  
Case No : AD00011389  
Vehicle No : SGY6189K  
Chassis : ZNE100380666  
Year of Mfr 2007  
Policy No 5116820775  
Model : TOYOTA WISH 1.8 A

### Term:

| Sn                                                                                   | DESCRIPTION | QTY | U_PRICE     | DISC | AMOUNT   |
|--------------------------------------------------------------------------------------|-------------|-----|-------------|------|----------|
|                                                                                      |             |     |             |      | 6447.56  |
| SINGAPORE DOLLARS : SIX THOUSAND SEVEN HUNDRED THIRTY-NINE AND CENTS NINETY-ONE ONLY |             |     | Less Excess |      | 0.00     |
|                                                                                      |             |     | SUBTOTAL    |      | 6,298.98 |
|                                                                                      |             |     | GST 7.00%   |      | 440.93   |
|                                                                                      |             |     | TOTAL       |      | 6,739.91 |

Date of accident : 28/10/2020 11:30 AM. Place : SLIP ROAD OF EXIT 27 PIE > TUAS

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

\* N = Item not subjected to GST