



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20011819/EUqf3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 04-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 3754T	Veh. Inspected	SHC 8182U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003149/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	30/10/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU090088	Colour	BLUE
Odometer	584746	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	MICHELIN	4 mm
L/H Front Tyre	205/60 R16	MICHELIN	4 mm
R/H Rear Tyre	205/60 R16	MICHELIN	4 mm
L/H Rear Tyre	205/60 R16	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/10/2020	Inspection Date	30/10/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------