



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0806/2020/NS
DATE : 27-Oct-20
WIP : 54572

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TEO LIAN BENG
ADDRESS : 1 BURGHLEY DRIVE
SINGAPORE 558974
TELEPHONE : HP +65 96688467
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070112668
VEHICLE NO : SLA 6669 J
MODEL CODE : AUDI Q3 SPORTSBACK 1.4 TFS
MODEL YEAR : 30/7/2020
ENGINE NO : CZD 893411
CHASSIS NO : WAUZZZF31L1101739
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Oct-20
PLACE OF ACCIDENT : ALONG SERANGOON GARDEN NEAR YIO CHU KANG



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 6669.1

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 ✓	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00 ✓	550 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,800.00 ✓	1775 ✓ 2.5 x 550 = 1375 60400 / 4rc x 0.2 = 200 x 2 = 400 <u>1775</u>
5	TO CARRY OUT CALIBRATION FOR FRONT RADAR SENSOR.	S/N \$ 280.00 ✓	7 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		\$ 9,352.00	



PREMIUM AUTOMOBILES



55 UBI ROAD I, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 6669J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1	FRONT BUMPER <i>Debond</i>	\$	2,615.00	✓ 2091.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	410.00	+
3	FRONT BUMPER CLOSING ELEMENT - LH ?	X NN \$	58.00	?
4	FRONT BUMPER TRIM ?	X NN \$	352.00	?
5	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	215.00	+
6	ULTRASOUND SENSOR SUPPORT - LH / RH ?	2 X \$ NN	50.00	?
7	RADIATOR GRILLE INNER COVER ?	X NN \$	51.00	?
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$	188.00	+
9	FRONT SPOILER <i>cut</i>	\$	754.00	✓ 603.20
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$	151.00	+
11	FRONT BUMPER AIR GUIDE GRILLE TRIM - LH <i>cut</i>	\$	162.00	✓ 129.20
12	FRONT BUMPER BRACKET ?	X NN \$	21.00	?
13	ULTRASOUND SENSOR BRACKET - LH <i>new</i>	\$	25.00	+
14	RADIATOR GRILLE <i>cracked</i>	\$	1,907.00	✓ 1525.60
15	RADIATOR GRILLE STRIKER PLATE ?	✓ cracked \$	241.00	?
16	RADIATOR GRILLE COVER ?	✓ cracked \$	241.00	?
17	RADIATOR GRILLE BRACKET ?	X NN \$	41.00	?
18	FRONT BUMPER CARRIER ?	X NN \$	834.00	?
19	FRONT BUMPER FOAM FILLER PIECE ?	X NN \$	101.00	?
20	FRONT BUMPER TOP COVER <i>new</i>	cracked \$	121.00	+
SUB TOTAL SPARE PARTS				\$ 8,538.00



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 6669 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	CAUTION SIGN STICKER 1 nec	NEC	\$ 14.00	* ✓ 10.80
22	AIRCON STICKER 1 nec	NEC	\$ 8.00	* ✓ 5.68
23	FRONT PARKING AID SENSOR	2	\$ 484.00	*
24	FRONT PARKING AID SEAL RING	4	\$ 14.00	*
25	SIGNAL HORN - LH HIGH TONE	\$	\$ 133.00	*
26	SPRING SHACKLE - LH	\$	\$ 22.00	*
27	FRONT BUMPER GUIDE SECTION - LH new	\$	\$ 38.00	*
28	FRONT FENDER - LH new	\$	\$ 1,271.00	*
29	FRONT FENDER ATTACHMENT PARTS	\$	\$ 62.00	*
30	FRONT FENDER BRACE - LH new	\$	\$ 87.00	*
31	FRONT FENDER BRACKET - LH new	\$	\$ 31.00	*
32	FRONT WHEEL HOUSING LINER - LH	\$	\$ 237.00	*
33	WHEEL HOUSING LINER ATTACHMENT PARTS new	\$	\$ 100.00	*
34	BONNET Repair	\$	\$ 3,468.00	*
35	BONNET ATTACHMENT PARTS new	\$	\$ 293.00	*
36	BONNET LID HINGE - LH / RH new	2	\$ 144.00	*
37	BONNET IMPACT PROTECTION - CENTRE new	\$	\$ 27.00	*
38	BONNET RELEASE ELEMENT new	\$	\$ 57.00	*
39	BONNET RELEASE LEVER new	\$	\$ 14.00	*
40	BONNET BOWDEN CABLE - CENTRE	\$	\$ 57.00	*
SUB TOTAL SPARE PARTS			\$ 6,561.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 6669J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
41	HEADLIGHT MOUNTING - LH 2 cracked	\$	117.00 ✓	93.60
42	LED HEADLIGHT - LH 2 cut	\$	5,526.00 ✓	4420.80
43	LIFT CYLINDER - LH 2 3 nec	\$	208.00 ✓	
44	LIFT CYLINDER HOSE 2 3 nec	\$	79.00 ✓	
45	RADIATOR AIR GUIDE - LH 2 cracked	\$	37.00 ✓	✓ 29.44
46	RADIATOR AIR GUIDE - UPPER 2 nn	\$	41.00 ✓	
47	FRONT WHEEL COVER - LH / RH 2 n/a	2	1,060.00 ✓	848
48	FRONT NO PLATE 1 dented	S/N	60.00 ✓	60
49	SUNDRIES 1 ✓ nec	\$	300.00 ✓	19.20

TOTAL SPARE PARTS	:	\$	22,527.00
TOTAL LABOUR CHARGES	:	\$	9,352.00
GRAND TOTAL	:	\$	31,879.00

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS :

Adrian
 29/10/20.

Not Authorised, 04 Days (Without Radar Calibration)
 05 Days (With Radar Calibration)

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT