

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9939C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	50.00	50.00
1	REINFORCEMENT SUB-AS (SN)	NOT NECESSARY	399.50	-
1	RETAINER, FR BUMPER (SN)	CRACKED	68.70	68.70
1	RETAINER, FR BUMPER (SN)	NOT NECESSARY	68.70	-
1	GRILLE, RADIATOR, LW (SN)	DEFORMED	287.60	287.60
1	COVER, FR BUMPER HOL (SN)	СИТ	59.70	59.70
1	GRILLE SUB-ASSY, RAD (SN)	NOT NECESSARY	204.10	-
1	MOULDING, RADIATOR G (SN)	NOT NECESSARY	69.40	-
1	MOULDING, RADIATOR G (SN)	NOT NECESSARY	69.40	-
1	SEAL, FR FENDER TO C (SN)	NOT NECESSARY	45.90	-
1	L/FRONT FENDER PANEL (SN)	BENT	706.80	706.80
1	LINER, FR FENDER, LH (SN)	TORN	303.40	303.40
1	SUPPORT SUB-ASSY, HO (SN)	NOT NECESSARY	149.40	-
1	EXTENSION, RADIATOR (SN)	NOT NECESSARY	65.80	-
1	SEAL, RADIATOR SIDE (SN)	NOT NECESSARY	80.70	-
1	SUPPORT, RADIATOR, U (SN)	NOT NECESSARY	78.90	-
1	HEADLAMP ASSY, RH (SN)	NOT NECESSARY	608.70	-
1	HEADLAMP ASSY, LH (SN)	CRACKED	608.70	608.70
1	COVER, FR BUMPER, L (SN) (ADDITIONAL)	DEFORMED	495.70	495.70
			4,421.10	2,580.60
	<u>LABOUR</u>			
	CHECK WIRING AND REFOCUS HEADLAMP.		180.00	180.00
	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA.		3,600.00	1,800.00
	RESPRAY ACC AFF AREA.		2,360.00	1,770.00
	RESET ECU UPON COMPLETION OF REPAIR.		180.00	180.00
			6,320.00	3,930.00
	GRAND TOTAL		10,741.10	6,510.60

RECOMMENDED COST OF REPAIRS			6,510.60
-----------------------------	--	--	----------

Report Ref No. CS/GAI20011821/T1vd3e2





Report Ref No. CS/GAI20011821/T1vd3e2

**MOHAMAD TAUFIKH** 

fourtim.

M.MATAI, AMSAE-A

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.