



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail		Account No	Customer Detail
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
		Document No	6 Shenton Way
		0	#38-01 Que Downtown
		Document Date	Singapore 068809
		29/10/2020	Work: 65703925

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	CEXRKT	Q1	NSP151R	17/03/2017	SLL9939C	0	57638 (6TP/SLL9939C/29102)
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFB29F3302008000	2NRX133735	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SDZ8863P ACC DATE:29/10/20 DRIVE IN:29/10/20 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:		Sundries		450 ✓
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP				180.00 ✓
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				1800 3600.00 ✓
4	B	BP-RES2 RESPRAY ACC AFF AREA				1770 2360.00 ✓
5	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				180.00 ✓
6	1	S52021-0D140 REINFORCEMENT SUB-AS	1.00	399.50		399.50 ✓
7	2	S52536-0D190 RETAINER, FR BUMPER	1.00	68.70		68.70 ✓
8	3	S52535-0D190 RETAINER, FR BUMPER	1.00	68.70		68.70 ✓
9	4	S53112-0D360 GRILLE, RADIATOR, LW	1.00	287.60		287.60 ✓
10	5	S52128-0D250 COVER, FR BUMPER HOL	1.00	59.70		59.70 ✓
11	6	S53101-0D904 GRILLE SUB-ASSY, RAD	1.00	204.10		204.10 ✓
12	7	S53124-0D140 MOULDING, RADIATOR G	1.00	69.40		69.40 ✓
13	8	S53121-0D200 MOULDING, RADIATOR G	1.00	69.40		69.40 ✓
14	9	S53867-0D160 SEAL, FR FENDER TO C	1.00	45.90		45.90 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.	Please acknowledge receipt of vehicle Parts Labour Materials Lubrication/Fluid Others	Total 77495749 30/10/20 @ 12pm Less WP Rework before paint 77495749 6 days	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD	Knownledged by Repairer	DATE	29/10/2020
PLEASE ALLOW THE UNDERMENTIONED	Signature	TIME	16:41
VEHICLE TO LEAVE THE COMPANY PREMISES.			

VEHICLE NO SLL9939C

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail		Account No S1000020/TPCLAIM		Customer Detail			
THIRD PARTY CLAIM		Document No 0		M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Que Downtown Singapore 068809			
		Document Date 29/10/2020		Work: 65703925			
Year	Make	Model	Reg Date	Veh Reg No	Kilometers		
17	CEXRKT	Q1	NSP151R	17/03/2017	SLL9939C		
					0		
					57638		
					6TP/SLL9939C/291021		
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFB29F3302008000	2NRX133735	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
15	0	S53812-K0020 L/FRONT FENDER PANEL		1.00	706.80		✓ 706.80
16	1	S53876-0D380 LINER, FR FENDER, LH		1.00	303.40		✓ 303.40
17	2	S53208-0D160 SUPPORT SUB-ASSY, HO		1.00	149.40		✓ 149.40
18	3	S53288-0D170 EXTENSION, RADIATOR		1.00	65.80		✓ 65.80
19	4	S53286-0D240 SEAL, RADIATOR SIDE		1.00	80.70		✓ 80.70
20	5	S53214-0D140 SUPPORT, RADIATOR, U		1.00	78.90		✓ 78.90
21	6	S81110-0D831 HEADLAMP ASSY, RH		1.00	608.70		✓ 608.70
22	7	S81150-0D831 HEADLAMP ASSY, LH		1.00	608.70		✓ 608.70
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						10,741.10	
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total 10,195.40	
		Please acknowledge receipt of vehicle		Parts 3,875.40		GST 7.00% 713.68	
				Labour 6,320.00		Less 0.00	
				Materials 0.00			
				Lubrication/Fluid 0.00			
				Others 0.00		Amount Due 10,909.08	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 29/10/2020
TIME 16:41

VEHICLE NO SLL9939C

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors

4300084

4300084