

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	GREAT AMERICA	N INSURANCE COMPANY	Ī	Ref:	CS/GAI20011825/Uvf3e2	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	AL TOWER	I	Date:	11/03/2021	
			(	Code:	GAI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GY 233E	Veh. Inspected		FBF 7258Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CLMOMVC000003901	Excess (\$)		0.00	
	Assign From	SHERY WONG	Assign Date		28/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CB400	c.c		399	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	JH2NC4295BK300129	Colour		BLACK	
	Odometer	231328 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/60Z R17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160/60Z R17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/10/2020	Inspection Date	)	30/10/2020	
	Survey held at	BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUK				
	Repairer	Repairer SANFU MOTOR PL				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	l .					