

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SDQ38E
Chassis No: ZWR800400881
Engine No: ZR0E20182

Report No: AMM2010-04
Date: 26.10.2020

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Rear Boot / <i>DD</i>	Damaged	\$ 2,212.50	\$ 1,991.25
2	1	Rear Boot Rubber Stopper <i>X N/A</i>	Necessary	\$ 121.60	\$ 109.44
3	1	Rear Centre Chrome Garnish <i>X N/A</i>	Scratches	\$ 968.80	\$ 871.92
4	1	Rear Boot Emblem <i>X N/A</i>	Necessary	\$ 268.40	\$ 241.56
5	1	Rear Bumper / <i>DD</i>	Necessary	\$ 973.50	\$ 876.15
6	1	Rear Bumper Reflector Left <i>X N/A</i>	Damaged	\$ 198.50	\$ 178.65
7	1	Rear Bumper Reflector Right <i>X N/A</i>	Impacted	\$ 198.50	\$ 178.65
8	1	Rear Boot Emblem 'hybrid logo' / <i>PC</i>	Necessary	\$ 148.70	\$ 133.83
9	1	Rear inner Panel <i>X R</i>	Impacted	\$ 168.70	\$ 151.83
10	1	Rear Fender Lamp With Chrome left <i>X</i>	Damaged <i>N/A</i>	\$ 991.60	\$ 892.44
12	1	Rear Boot Lock / <i>MT</i>	Jammed	\$ 668.90	\$ 602.01
13	1	Rear Boot Damper <i>X N/A</i>	Necessary	\$ 310.40	\$ 279.36
14.3	1	Door Lock Hinge <i>X N/A</i>	Distorted	\$ 128.90	\$ 116.01
15.6	1	Rear End Panel / <i>DD</i>	Impacted	\$ 775.80	\$ 698.22
				\$ 8,134.80	\$ 6,507.84

Total (Parts): \$ 8,134.80 Less 20% \$ 6,507.84

Labour Charges

26	To fix & dismantle and remove damaged Rear Portions; affected damaged portion.	\$ 1,000.00
27	To apply anti rust coat and affected areas	\$ 120.00
28	To check wiring	\$ 120.00
29	Welding and cutting of affected panels, including chassis alignment.	\$ -
30	Spray painting for Front and Rear Portions affected parts	\$ 1,200.00
31	To apply waterproofing sealer on end panels	\$ 120.00
32	Diagnose ECU system and reset error code.	\$ 120.00
33	3D Wheel Alignment	\$ 180.00
Total Labour:		\$ 2,860.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 9,367.84

Less 20% \$ 7,494.27

AMM PTE LTD

Stere (LKK)
83228813

W/L Pm
30/10/20, 2 days
5 days
L/S
My AL

Page 2 of 3

Ynsqmo2 z/W

smB1 toyeu2

Ynsqmo2 toyeu2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: