



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Tan Kee Seng(Chen Qicheng) ADDRESS : Blk 441d Fernvale Road #13-339 Singapore 794441 TEL : 90888148		WIP : 39408 EXCESS : NIL DATE: 28-Oct-20	
VEH NO :	SMJ9545D	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6DK2W7AK0416012	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX-3	DATE REG.:	26-Mar-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MDHYF-50-22XABB	\$ 1,040.10	\$ 1,040.10
2	2	MD10J-50-271	\$ 52.20	\$ 52.20
3	6	MBGV4-56-145	\$ 17.40	\$ 17.40
4	1	MD10J-50-1K5	\$ 3.90	\$ 3.90
5	6	MBHN1-50-0Z1A	\$ 16.20	\$ 16.20
6	2	MG043-62-864A	\$ 7.00	\$ 7.00
7	10	MB45A-56-146A	\$ 30.00	\$ 30.00
8	4	MC274-50-133	\$ 14.80	\$ 14.80
9	2	MG001-67-061	\$ 15.60	\$ 15.60
10	2	MGHP9-67-UC5	\$ 22.60	\$ 22.60
11	2	MGM8C-67-UC1	\$ 401.00	\$ 401.00
12	1	MD10J-50-C51		\$ 42.60
13	1	MD10J-50-371		\$ 17.10
14	1	MD82P-50-260A	\$ 362.80	\$ 362.80
15	1	MDKY0-62-02XC	\$ 1,089.90	\$ 1,089.90
16	1	MGJ6A-68-966 02		\$ 23.10
17	1	MD10E-62-866A		\$ 16.20
18	5	MGJ21-68-885B02	\$ 15.00	\$ 15.00
19	4	MD24H-62-866	\$ 10.00	\$ 10.00
20	1	MBHN1-56-8D0B		\$ 109.20
21	1	MD10E-62-4B0B		\$ 86.80
22	1	MDM0P-62-310		\$ 212.30
23	3	MEG21-51-146	\$ 18.60	\$ 18.60
24	2	MBF67-51-261	\$ 4.80	\$ 4.80
25	2	MC513-50-896	\$ 16.40	\$ 16.40
26	2	MD204-50-896A	\$ 5.60	\$ 5.60
27	3	MGJ6A-50-897	\$ 38.40	\$ 38.40
28	1	MD11B-51-730	\$ 54.30	\$ 54.30
29	1	MD10J-51-721	\$ 55.70	\$ 55.70
30	1	MD10J-51-771A	\$ 56.60	\$ 56.60

31	ANTENNA		1	MKD47-67-6NXA		\$	111.10	
32	CLIP ,ANTENNA		1	MKD45-67-6NYA		\$	2.70	
33	CAMERA-BACK		1	MD24M-67-RCO		\$	793.80	
34	SILENCER		1	MPEG8-40-100A		\$	1,349.30	
35	HANGER, SILENCER		4	MBP47-40-061A		\$	140.00	
36	CONVERTER		1	MPEG8-20-55X		\$	1,278.70	
37	HANGER, COVERTER		1	MKL16-40-061		\$	28.40	
38	RUBBER, HANGER		2	MPE70-40-061		\$	57.00	
39	GASKET, EXHAUST		2	MP549-40-305		\$	30.80	
SUPPLEMENTARY ITEMS:								
1	GASKET LHS, TAILGATE	ADD	1	MDB3D-51-3J8	<i>NA</i>	\$	41.30	\$ 41.30
2	GASKET RHS, TAILGATE	ADD	1	MDB3D-51-3H8	<i>NA</i>	\$	41.30	\$ 41.30
TOTAL PARTS						\$	3,431.50	\$ 7,730.60
TOTAL PARTS COST						\$	3,431.50	\$ 7,730.60

Labour Description

1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$	1,320.00	\$	2,640.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.	\$	1,575.00	\$	2,520.00
3	MZ-BR-SPOILER	TO REMOVE & REFIX SPOILER TAILGATE	\$	180.00	\$	180.00
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$	200.00	\$	560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$	120.00	\$	120.00
6	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	\$	330.00	\$	330.00
7	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.			\$	990.00
8	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$	180.00	\$	330.00
9	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$	180.00	\$	330.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.			\$	70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$	120.00	\$	250.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$	120.00	\$	250.00

13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
14	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		\$ 100.00
15	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00

TOTAL LABOUR	\$ 4,495.00	\$ 9,120.00
TOTAL PARTS	\$ 3,431.50	\$ 7,730.60
TOTAL	\$ 7,926.50	\$ 16,850.60
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 7,926.50	
GST 7%	\$ 554.86	\$ -
GRAND TOTAL	\$ 8,481.36	\$ -

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)