



Not Author  
all  
who pho before party  
4/11/20  
5 days.

TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

24 NOV 2020

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Tan Kee Seng(Chen Qicheng) ADDRESS: Blk 441d Fernvale Road #13-339 Singapore 794441 TEL: 90888148	WIP: 39408 EXCESS: DATE: 28-Oct-20 LKY
VEH NO:	SMJ9545D	DATE IN:	CONTACT PERSON: Ronald 63957875
CHASSIS NO:	JM6DK2W7AK0416012	MILEAGE:	TYPE OF CLAIM: THIRD PARTY CLAIM
MODEL:	CX-3	DATE REG.: 26-Mar-19	POLICY NO.:

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES		
1	REAR BUMPER	1	MDHYF-50-22XABB	D.S ✓	\$ 1,040.10
2	BRACKET CENTER	2	MD10J-50-271	D.S ✓	\$ 52.20
3	CLIP, REAR BUMPER	6	MBGV4-56-145	re ✓	\$ 17.40
4	PIN LOCATOR, REAR BUMPER	1	MD10J-50-1K5	re ✓	\$ 3.90
5	GROMMET, REAR BUMPER	6	MBHN1-50-0Z1A	re ✓	\$ 16.20
6	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	re ✓	\$ 7.00
7	FASTENER, REAR BUMPER	10	MB45A-56-146A	re ✓	\$ 30.00
8	NUT CLIP, REAR BUMPER	4	MC274-50-133	re ✓	\$ 14.80
9	PAD PROTECTOR, REAR BUMPER	2	MG001-67-061	D.S ✓	\$ 15.60
10	RETAINER CENTER, SENSOR	2	MGHP9-67-UC5	re ✓	\$ 22.60
11	SENSOR CENTER, ULTRASONIC	2	MGMC8-67-UC1	slud ✓	\$ 401.00
12	COVER UNDER, REAR BUMPER	1	MD10J-50-C51	re X	\$ 42.60
13	GUARD CENTER, REAR BUMPER	1	MD10J-50-371	re X	\$ 17.10
14	REAR REINFORCEMENT	1	MDB2P-50-260A	PIS ✓	\$ 362.80
15	TAILGATE	1	MDKY0-62-02XC	Boilers ✓	\$ 1,089.90
16	RECESS, TAILGATE	1	MGJ6A-68-966 02	re X	\$ 23.10
17	RUBBER HOLE, TAILGATE	1	MD10E-62-866A	re X	\$ 16.20
18	FASTENER, TAILGATE	5	MGJ21-68-885B02	re ✓	\$ 15.00
19	COVER,HOLE, TAILGATE	4	MD24H-62-866	re ✓	\$ 10.00
20	SWITCH, TAILGATE	1	MBHN1-56-8DOB	re X	\$ 109.20
21	SWITCH OPEN, TAILGATE	1	MD10E-62-4B0B	re X	\$ 86.80
22	LOCK, TAILGATE	1	MDM0P-62-310	re X	\$ 212.30
23	FASTENER, TAILGATE	3	MEG21-51-146	re ✓	\$ 18.60
24	GROMMET, TAILGATE	2	MBF67-51-261	re ✓	\$ 4.80
25	FASTENER, REAR WINDSCREEN	2	MC513-50-896	re ✓	\$ 16.40
26	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	re ✓	\$ 5.60
27	, REAR WINDSCREENSPACER	3	MGJ6A-50-897	re ✓	\$ 38.40
28	MASCOT, REAR	1	MD11B-51-730	re ✓	\$ 54.30
29	ORNAMENT, CX-3	1	MD10J-51-721	re ✓	\$ 55.70
30	ORNAMENT, SKYACTIV	1	MD10J-51-771A	re ✓	\$ 56.60

31	ANTENNA	1	MKD47-67-6NXA	MX	\$ 111.10
32	CLIP ,ANTENNA	1	MKD45-67-6NYA	MX	\$ 2.70
33	CAMERA-BACK	1	MD24M-67-RC0	MX	\$ 793.80
34	SILENCER	1	MPEG8-40-100A	11X	\$ 1,349.30
35	HANGER, SILENCER	4	MBP47-40-061A	11X	\$ 140.00
36	CONVERTER	1	MPEG8-20-55X	11X	\$ 1,278.70
37	HANGER, COVERTER	1	MKL16-40-061	11X	\$ 28.40
38	RUBBER, HANGER	2	MPE70-40-061	11X	\$ 57.00
39	GASKET, EXHAUST	2	MP549-40-305	MX	\$ 30.80
<b>TOTAL PARTS</b>					\$ 7,648.00
<b>TOTAL PARTS COST</b>					\$ 7,648.00

**Labour Description**

1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1320		\$ 2,640.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. 2.5'	1525		\$ 2,520.00
3	MZ-BR-SPOILER	TO REMOVE & REFIX SPOILER TAILGATE			\$ 180.00 ✓
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST. 200	NETT		\$ 560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS. nu	NETT		\$ 120.00 ✓
6	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.			\$ 330.00 ✓
7	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY. 11X	NETT		\$ 990.00
8	MZ-BR-REVTEN	TO TRANSFER REVERSE SENSORS. 180			\$ 330.00
9	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA. 180			\$ 330.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. MX	NETT		\$ 70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 120			\$ 250.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. 120			\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. 150			\$ 350.00
14	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. 11X	NETT		\$ 100.00

15	MZ-BR-SUNDRI	SUNDRIES.			
				NETT	\$ 100.00
			Nett 20		
			TOTAL LABOUR	\$ -	\$ 9,120.00
			TOTAL PARTS	\$ -	\$ 7,648.00
			TOTAL	\$ -	\$ 16,768.00
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**TRANS EUROKARS PTE LTD**

\_\_\_\_\_  
 Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

31	ANTENNA		1	MKD47-67-6NXA		\$	111.10	
32	CLIP ,ANTENNA		1	MKD45-67-6NYA		\$	2.70	
33	CAMERA-BACK		1	MD24M-67-RCO		\$	793.80	
34	SILENCER		1	MPEG8-40-100A		\$	1,349.30	
35	HANGER, SILENCER		4	MBP47-40-061A		\$	140.00	
36	CONVERTER		1	MPEG8-20-55X		\$	1,278.70	
37	HANGER, COVERTER		1	MKL16-40-061		\$	28.40	
38	RUBBER, HANGER		2	MPE70-40-061		\$	57.00	
39	GASKET, EXHAUST		2	MP549-40-305		\$	30.80	
<b>SUPPLEMENTARY ITEMS:</b>								
1	GASKET LHS, TAILGATE	<b>ADD</b>	1	MDB3D-51-3J8	<i>NA</i>	\$	41.30	\$ 41.30
2	GASKET RHS, TAILGATE	<b>ADD</b>	1	MDB3D-51-3H8	<i>NA</i>	\$	41.30	\$ 41.30
<b>TOTAL PARTS</b>						\$	3,431.50	\$ 7,730.60
<b>TOTAL PARTS COST</b>						\$	3,431.50	\$ 7,730.60

Labour Description

1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$	1,320.00	\$	2,640.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.	\$	1,575.00	\$	2,520.00
3	MZ-BR-SPOILER	TO REMOVE & REFIX SPOILER TAILGATE	\$	180.00	\$	180.00
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$	200.00	\$	560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$	120.00	\$	120.00
6	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	\$	330.00	\$	330.00
7	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.			\$	990.00
8	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$	180.00	\$	330.00
9	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$	180.00	\$	330.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.			\$	70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$	120.00	\$	250.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$	120.00	\$	250.00