



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI20011851/Usd3e2

5 MAXWELL ROAD #17-00 TOWER BLOCK MND  
COMPLEXSINGAPORE 069110

Date : 26-11-2020



Code : EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YN 4000D	<b>Veh. Inspected</b>	SMJ 9545D
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DM20HO01598/JT	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JANICE GOH	<b>Assign Date</b>	30/10/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA CX-3 (A)	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	JM6DK2W7AK0416012	<b>Colour</b>	GREY
<b>Odometer</b>	17364	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R18	TOYO	8 mm
<b>L/H Front Tyre</b>	215/60 R18	TOYO	8 mm
<b>R/H Rear Tyre</b>	215/60 R18	TOYO	8 mm
<b>L/H Rear Tyre</b>	215/60 R18	TOYO	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	28/10/2020	<b>Inspection Date</b>	04/11/2020
<b>Survey held at</b>	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**