



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1580A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER BRACKET/RH	NOT NECESSARY	55.80	-
	LESS 20% DISCOUNT		-103.04	-
			412.16	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR APP STICKER (SN)	NECESSARY	80.00	80.00
			80.00	80.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		320.00	320.00
	SPRAY PAINTING CHARGE.		700.00	600.00
			1,020.00	920.00
	GRAND TOTAL		1,512.16	1,000.00
RECOMMENDED COST OF REPAIRS				1,000.00

Report Ref No. NS/INC20011852/Etf3q2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.