

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/III/AMK

Claim Type: Third Party

Accident Date: 30/10/2020

TP Veh Reg No: SHA4023H

Estimate No: ES2090872/AMK

Date: 30 Oct 2020

Policy No: 5092790250-03

Veh Reg No: SLR532U

Make/Model: HONDA VEZEL 1.5X
AUTO

Chassis No: RU31248864

Engine No: LEB5948881

Reg. Date: 28/07/2017

Estimate Repair Cost to Vehicle No :SLR532U

Description	U/Price	Quantity	List Price	Amount
List Price			S\$	S\$
1 REAR BUMPER	798.10	1 PC	798.10	✓
2 REAR BUMPER CLIP	3.80	5 PC	19.00	✓
3 REAR TAILGATE	997.70	1 PC	997.70	✓
4 TAILGATE INNER LOCK	96.70	1 PC	96.70	✓
5 TAILGATE INNER RUBBER	101.40	1 PC	101.40	✓
6 TAILGATE EMBLEM 'HYBRID'	66.30	1 PC	66.30	✓
7 TAILGATE EMBLEM 'VEZEL'	43.00	1 PC	43.00	✓
8 TAILGATE WINDSCREEN GLASS MOULDING	109.30	1 PC	109.30	✓
9 REAR END PANEL	411.90	1 PC	411.90	✓
10 REAR END PANEL INNER TOP GARNISH	80.60	1 PC	80.60	✓
11 REAR END PANEL BUZZER SENSOR	85.00	1 PC	85.00	✓
12 REAR END PANEL ANTENNA	58.10	1 PC	58.10	✗
13 REAR LUGGAGE COMPARTMENT PANEL	787.50	1 PC	787.50	✓
14 REAR LUGGAGE COMPARTMENT TOP BOARD	430.30	1 PC	430.30	✓
15 REAR LUGGAGE TOOL BOX	137.30	1 PC	137.30	✓
16 REAR LUGGAGE COMPARTMENT PANEL LOWER UNDER COVER	190.00	1 PC	190.00	✓
17 REAR EXHAUST MUFFLER	552.50	1 PC	552.50	7 R
			4,964.70	
		Less 20%	992.94	3,971.76
Special Net				
18 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
19 REVERSE SENSOR	200.00	1 SET	200.00	✓
20 REAR END PANEL SEALANT	40.00	1 PC	40.00	✓
21 REAR LUGGAGE COMPARTMENT PANEL TOP COAT	100.00	1 PC	100.00	60.00
			380.00	380.00
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
23 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILGATE, SPOILER & ATTACHMENTS, TAILLAMP; TO CUT, WELD & RENEW REAR END PANEL, REAR LUGGAGE PANEL; KNOCKING & REPAIR REAR CHASSIS FRAME & REALIGN THE SAME	1,100.00	1 LA	1,100.00	900
24 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR END PANEL, REAR LUGGAGE PANEL, REAR CHASSIS FRAME & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	900

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

WS Ref: TP/III/AMK
 Claim Type: Third Party
 Accident Date: 30/10/2020
 TP Veh Reg No: SHA4023H

Estimate No: ES2090872/AMK
 Date: 30 Oct 2020
 Policy No: 5092790250-03
 Veh Reg No: SLR532U
 Make/Model: HONDA VEZEL 1.5X
 AUTO
 Chassis No: RU31248864
 Engine No: LEB5948881
 Reg. Date: 28/07/2017

Estimate Repair Cost to Vehicle No :SLR532U

Description	U/Price	Quantity	List Price	Amount
25 REMOVE & REFIX REAR FENDER GARNISHS, SEAT TO FACILITATE REPAIR	150.00	1LA	150.00	100%
26 REMOVE & REFIX REAR MUFFLER & REALIGN THE SAME	80.00	1LA	80.00	60%
27 RUSTPROOFING	90.00	1LA	90.00	60%
28 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	60.00	1PC	60.00	
			2,600.00	2,600.00
			Total	S\$ 6,951.76
			Add GST @ 7%	486.62
			Total Amount Payable	S\$ 7,438.38

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

workshop

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AUTHORISED SIGNATURE

20% \$4354.10
 \$870.82
 \$3483.28
 340.91
 2500
 314.88
 \$6638.16

V/S: \$5300

② days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLR532 U

SUPP 1

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES2090872/AMK

Date: 02 Nov 2020

Policy No: 5092790250-03

Veh Reg No: SLR532U

Make/Model: HONDA VEZEL 1.5X
AUTO

Chassis No: RU31248864

Engine No: LEB5948881

Reg. Date: 28/07/2017

WS Ref: TP/III/AMK

Claim Type: Third Party

Accident Date: 30/10/2020

TP Veh Reg No: SHA4023H

Estimate Repair Cost to Vehicle No :SLR532U

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 TAILGATE OUTER GARNISH	193.60	1 PC	193.60	✓ cra
			193.60	
		Less 20%	38.72	154.88
Labour				
2 REMOVE & REFIX HYBRID BATTERY AND RESET SYSTEM	200.00	1 LA	200.00	160✓
			200.00	200.00
			Total	S\$ 354.88
			GST Amount	S\$ 24.84
			Total Amount Payable	S\$ 379.72

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE