

SMJ635Z.

TPA16.

Shirley

Toyota CHR 1797CC

ZYX102142660.

Rear Bumper.	Dehd	1030 ✓
Rear Bumper Clips.	~	30 ✓
Rear Bumper Side Holder x 02	} 14 ~	$62.3 \times 2 = 124.60 +$
Rear Bumper Side Garnish x 02		$92.7 \times 2 = 185.40 +$
Rear Bumper Reflector x 02.		$62.3 \times 2 = 124.60 +$
Rear Bumper Tow Covers.	Dehd	32.70 ✓
Rear Bumper Lower Garnish.	Dehd	620 ✓
Rear Bumper Reinforcement.	Best	482.50 —
Rear End Panel	Repr	689.30 +
Rear End Panel Top Garnish.	~	295.50 +
Rear End Panel Sealant.	~	60(SN) x.
Reverse Sensor.	Dehd	<del>280(SN)</del> 200(SN)
Tailgate Outer Garnish	Repr	882.20. +
Tailgate Outer Garnish Clips.	~	20(SN) x
Oscar's ToyPet Emblem	~	40(SN) ✓

SMJ6B5Z.

Panel Beating.

~~800~~ 300

Spray Painting.

~~800~~ 350

Wiring

~~50~~ 30

To remove reverse sensor

~~100~~ 50

To remove upholstery.

150. X.

\$5,672.60

hist: 215512

len 25% 146.40

S.N: 240

Labour: 730.

total: 2616.40

L/S: 2.1K

03 Days.

2.1K.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: