

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

 Model : **Nissan Sunny 1.6 EXM**

 Registraion No : **SFB 3373 Y**

 Chassis No: **JN1CFAN16Z0131341**

 Year of Manufacturing: **2008**

S/No	Qty	Items	Unit Price	Amount
1	1	Bootlid <i>one</i>	\$ 655.50	\$ 655.50 ✓
2	1	Bootlid Lock <i>BT</i>	\$ 59.50	\$ 59.50 43.3
3	1	Bootlid Lock Mechanism <i>X</i>	\$ 68.20	\$ 68.20
4	1	Bootlid Hinge (LH) <i>X</i>	\$ 98.40	\$ 98.40
5	1	Bootlid Hinge (RH) <i>X</i>	\$ 98.40	\$ 98.40
6	1	Bootlid Upper Chrome Moulding <i>one</i>	\$ 351.30	\$ 351.30 ✓
7	1	Bootlid Lower Chrome Moulding	\$ 216.40	\$ 216.40 173.8
8	1	Bootlid Logo	\$ 84.40	\$ 84.40 33.2
9	1	Bootlid Emblem - Sunny <i>one</i>	\$ 84.40	\$ 84.40 56.2
10	1	Bootlid Emblem - EX Saloon	\$ 84.40	\$ 84.40 56.2
11	1	Bootlid Insulator <i>X NN</i>	\$ 214.50	\$ 214.50
12	1	Tail Lamp (RH) <i>CRA</i>	\$ 425.70	\$ 425.70 263.2
13	1	Tail Lamp Panel (RH) <i>X NN</i>	\$ 174.80	\$ 174.80
14	1	Tail Lamp (LH) <i>CRA</i>	\$ 425.70	\$ 425.70 263.2
15	1	Tai Lamp Panel (LH) <i>X NN</i>	\$ 174.80	\$ 174.80
16	1	Rear Bumper <i>one</i>	\$ 487.50	\$ 487.50 433.5
17	1	Rear Bumper Retainer (LH) <i>one</i>	\$ 42.70	\$ 42.70 35
18	1	Rear Bumper Retainer (RH) <i>one</i>	\$ 42.70	\$ 42.70 35
19	1	Rear Bumper Bracket (LH) <i>X</i>	\$ 45.50	\$ 45.50
20	1	Rear Bumper Bracket (RH) <i>X</i>	\$ 45.50	\$ 45.50
21	1	Rear Bumper Reinforcement <i>X NN</i>	\$ 365.10	\$ 365.10
22	1	Rear Bumper Sponge <i>X CRA</i>	\$ 184.70	\$ 184.70 133.8
23	1	End Panel <i>one</i>	\$ 476.20	\$ 476.20 376.2
24	1	End Panel Top Garnish <i>one</i>	\$ 85.40	\$ 85.40 69.6
25	1	Spare Tyre Compartment <i>X Refert.</i>	\$ 871.40	\$ 871.40
26	1	Spare Tyre Compartment Board <i>X NN</i>	\$ 184.70	\$ 184.70

\$ 6,047.80 2979

-20% \$ 1,209.56

Total for spare parts \$ 4,838.24

Special Nett

1	10	Rear Bumper Clip <i>one</i>	\$ 5.00	\$ 50.00 30
2	10	End Panel Top Garnish Clip <i>X</i>	\$ 5.00	\$ 50.00
3	1	Reverse sensor <i>DM</i>	\$ 300.00	\$ 300.00 200
4	1	End Panel Sealant <i>one</i>	\$ 80.00	\$ 80.00 40

Total for SP \$ 480.00 270

Sub-Total for Parts : \$ 5,318.24

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	800.00 <i>600</i>
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,000.00 <i>700</i>
3		Apply rust proofing on the adjacent panels	\$	60.00 <i>50</i>
4		To supply under coating / putty on parts replaced	\$	60.00
5		To perform water seepage test after repair	\$	80.00 <i>X m</i>
6		Disconned and check electrical wiring, harness, wire socket	\$	80.00 <i>30</i>
7		To remove and refit bumper sensor	\$	60.00 <i>40</i>
8		Remove and refit rear end panel lining and garnish to facilitate repair	\$	80.00 <i>60</i>
				1480

TOTAL AMOUNT : \$ 2,220.00
OVERALL COST: \$ 7,538.24

5 Days.

4431.1

-20%: 3500

Unpshn repair.

After repair photos.

Gme Q10up

20/10/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: