

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
 6 RAFFLES QUAY #21-00
 SINGAPORE 048580

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP20/039

Date : 23/11/2020
 Vehicle Num. : SLN 9527Y
 Make/Model : MAZDA 6-2016
 Chassis/Eng# : JM6GL1071H0107340/PE20848533
 Accident Date : 30/10/2020
 Claim No. :
 Reference : LYB/SLN9527Y/MSFirst/tp/sl
 Policy No. :

Not Authorized
11 Rmp @ 3400/hr
Repair After Paint
3 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|---|----------------------------------|--|--|
| 1. | 1 | NETT ITEMS : | | |
| 2. | 2 | FRONT HEADLAMP/RH | | |
| 3. | 1 | FRONT HEADLAMP BRACKET/RH | | |
| 4. | 2 | FRONT BUMPER | | |
| 5. | 1 | FRONT BUMPER RETAINER | | |
| 6. | 1 | FRONT BUMPER SIDE MLDG | | |
| 7. | 1 | FRONT BUMPER LOWER GRILLE/CENTRE | | |
| 8. | 1 | FRONT BUMPER REINFORCEMENT | | |
| 9. | 2 | FRONT GRILLE | | |
| 10. | 8 | FRONT GRILLE CHROME LOWER | | |
| 11. | 1 | FRONT GRILLE CLIPS | | |
| 12. | 1 | FRONT GRILLE EMBLEM | | |
| 13. | 1 | FRONT RADIATOR TOP PANEL | | |
| 14. | 1 | FRONT WIPER TANK | | |
| 15. | 1 | FRONT FOGLAMP COVER/RH | | |

SLN	112.00	1,950.00	✓
SLN		224.00	X
SLN		895.90	✓
SLN	89.60	179.20	✓
SLN		119.60	✓
SLN		198.20	X
SLN		566.50	X
SLN		425.30	✓
SLN	112.00	224.00	✓
SLN	3.00	24.00	✓
SLN		128.70	✓
SLN		319.60	✓
SLN		89.60	X
SLN		89.90	X

Nett Total S\$:

5,434.50

10.00% Discount S\$:

543.45

20%

4,891.05

- | | | | | |
|----|-------|----------------------------------|--|--|
| 1. | 2 | SPECIAL NETT ITEMS : | | |
| 2. | 4 | FRONT BUMPER SENSOR | | |
| 3. | 1 SET | FRONT RIVETS | | |
| | | FRONT NO PLATE (EMBOSS) + HOLDER | | |

SLN	220.00	440.00	✓
SLN	5.00	20.00	✓
SLN		55.00	X

Special Nett Total S\$:

515.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
 6 RAFFLES QUAY #21-00
 SINGAPORE 048580

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP20/039

Date : 23/11/2020
 Vehicle Num. : SLN 9527Y
 Make/Model : MAZDA 6-2016
 Chassis/Eng# : JM6GL1071H0107340/PE20848533
 Accident Date : 30/10/2020
 Claim No. :
 Reference : LYB/SLN9527Y/MSFirst/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION	55.00	201
		TO REPLACE FRT SENSOR & CHECK SENSOR WIRING	120.00	601
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS	na 120.00	X
		TO COMPUTERISE WHEEL ALIGNMENT	na 120.00	X
		TO REPAIR PANEL BEAT, RE-STRAIGHTEN ON FRT SUPPORT PANEL, LABOUR TO REPLACE ABOVE PARTS	700.00	3001
		TO PUTTY, PRIMER & SPRAY PAINT ON FRT BUMPER, FRT SENSOR FRT RADIATOR TOP PANEL, RIGHT FRT AFFECTED FENDER & FRT AFFECTED BONNET USING 2K PAINT	1,200.00	4001
		Labour Total S\$:		2,315.00



E. & O.E.

Total S\$: 7,721.05
 =====

for LIM YEW BOO SPRAY PAINT CO.