

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20011903/ABA3Q2
Date: 12/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993817
Claimant Vehicle No :	SMN7418E	Insured Vehicle No :	GBG3933C
Date of Loss:	29/10/2020	Nature of Claim:	TP
		Claim No:	5949976379SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN7418E		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	2NR5367916
Reg. Date:	27/08/2019 (Man. Year: 2019)	Chassis No:	MR2B23F3701180375
Colour:	Silver	Odometer:	19666 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,581.77	2,896.82	2,684.95	48.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,610.00	840.00	34.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,031.77	4,506.82	3,524.95	43.89
Approved Total (Overridden) (S\$)		3,600.00		

(S\$)	8,031.77	3,600.00	4,431.77	55.18
+ GST 7.00/7.00% (S\$)	562.22	252.00	310.22	55.18
Nett Amount (S\$)	8,593.99	3,852.00	4,741.99	55.18
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		10.00		
Nett Liability (S\$)		4,562.00		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment: 30/10/2020

Date Inspected: 30/10/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	482.20 FL	*482.20 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	316.10 FL	*316.10 FL
3	1		*REAR BUMPER SIDE RETAINER	N/S Necessary	287.00 FL	*143.50 FL
4	1		*REAR BUMPER SMALL RETAINER	N/S Damaged	145.40 FL	*72.70 FL
5	1		*REAR BUMPER MUDFLAP LH	Not Necessary	76.90 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Cracked	92.80 FL	*92.80 FL
7	1		*BOOT LID	Dented	855.50 FL	*855.50 FL
8	1		*BOOT LID LOGO	Necessary	52.20 FL	*52.20 FL
9	1		*BOOT LID VIOS EMBLEM	Necessary	43.60 FL	*43.60 FL
10	1		*BOOT LID E EMBLEM	Necessary	38.60 FL	*38.60 FL
11	1		*BOOT LID LOCK	Damaged	320.40 FL	*320.40 FL
12	1		*BOOT LID LOCK CHECKER	Not Necessary	38.90 FL	*- FL
13	1		*BOOT LID RUBBER	Cut	166.40 FL	*166.40 FL
14	1		*BOOT LID TRIM	Not Necessary	278.90 FL	*- FL
15	1		*BOOT LID LAMP LH	Not Necessary	228.40 FL	*- FL
16	1		*BOOT LID LAMP RH	Not Necessary	228.40 FL	*- FL
17	1		*TAIL LAMP LH	Cracked	397.10 FL	*397.10 FL
18	1		*TAIL LAMP RH	Not Necessary	397.10 FL	*- FL
19	1		*REAR PANEL	Repair	728.70 FL	*- FL
20	1		*REAR PANEL TRIM	Deformed	242.30 FL	*242.30 FL
21	1		*REAR FENDER TRIM LH	Not Necessary	355.90 FL	*- FL
22	1		*SPARE TYRE COVER	Not Necessary	206.90 FL	*- FL
23	1		*REAR LOCK SENSOR	Damaged	165.70 FL	*165.70 FL
24	1		*REAR NUMBER PLATE LAMP GARNISH	Not Necessary	130.30 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
26	2		*L PLATE	Necessary	70.00 FS	*70.00 FS
27	1		*SET REAR BUMPER STICKER	Necessary	280.00 FS	*200.00 FS
28	1		*SET BOOTLID TRIM CLIPS	Not Necessary	40.00 FS	*- FS
29	1		*BOOT LID NUMBER 638 STICKER	Necessary	35.00 FS	*35.00 FS
30	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
31	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
32	1		*SET REAR FENDER TRIM CLIPS LH	Not Necessary	40.00 FS	*- FS
33	1		*REAR FENDER STICKER	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)

7,150.70

3,744.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					1,568.93	847.28
Total Parts (S\$)					5,581.77	2,896.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REPLACE STICKERS	New	160.00	80.00
3	TO SPRAY UNDERSEAL	New	120.00	40.00
4	(REAR) TO SPRA PAINTING	New	1,000.00	700.00
5	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,000.00	700.00
6	TO REMOVE AND REFIT INNER TRIM	New	120.00	60.00
Gross Labour Cost (S\$)			2,450.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >