

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000236
Date: 30 Oct 2020
Veh Reg No: SMN7418E
Make/Model: TOYOTA VIOS 1.5 E (AUTO)
Chasis No: MR2B23F3701180375
Reg. Date: 27/08/2019
Your Ref No: GBG3933C

Claim Type: Third Party
Accident Date: 30/10/2020
TP Veh Reg No: GBG3933C

Jasper

Estimate Repair Cost to Vehicle No :SMN7418E

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR BUMPER <i>Debond</i>	482.20	✓
2	1 PC REAR BUMPER REINFORCEMENT <i>Bent</i>	316.10	✓
3	2 PCS REAR BUMPER SIDE RETAINER <i>New LH R</i>	287.00 <i>143.52</i>	
4	2 PCS REAR BUMPER SMALL RETAINER <i>LH Dmg</i>	145.40 <i>72.70</i>	
5	1 PC REAR BUMPER MUDFLAP LH <i>Abc m</i>	76.90	+
6	1 PC REAR BUMPER REFLECTOR - LH <i>Amld</i>	92.80	✓
7	1 PC BOOT LID <i>Debond</i>	855.50	✓ <i>659</i>
8	1 PC BOOT LID LOGO	52.20	✓
9	1 PC BOOT LID "VIOS" EMBLEM <i>New</i>	43.60	✓
10	1 PC BOOT LID "E" EMBLEM	38.60	✓
11	1 PC BOOT LID LOCK <i>Dmg</i>	320.40	✓
12	1 PC BOOT LID LOCK CHECKER <i>Abc m</i>	38.90	+
13	1 PC BOOT LID RUBBER <i>New LH</i>	166.40	✓
14	1 PC BOOT LID TRIM <i>Abc m</i>	278.90	x
15	1 PC BOOT LID LAMP LH <i>Abc m</i>	228.40	+
16	1 PC BOOT LID LAMP RH <i>Abc m</i>	228.40	+
17	1 PC TAIL LAMP LH <i>Amld</i>	397.10	✓
18	1 PC TAIL LAMP - RH <i>Abc m</i>	397.10	+
19	1 PC REAR PANEL <i>Regis</i>	728.70	+
20	1 PC REAR PANEL TRIM <i>Debond</i>	242.30	✓
21	1 PC REAR FENDER TRIM LH <i>Abc m</i>	355.90	+
22	1 PC SPARE TYRE COVER <i>Abc m</i>	206.90	+
23	1 PC REAR LOCK SENSOR <i>New Dmg</i>	165.70	✓
24	1 PC REAR NUMBER PLATE LAMP GARNISH <i>New</i>	130.30	+
		6,275.70	
	Less 25%	1,568.93	4,706.84
	Special Net		
25	1 SET REAR BUMPER CLIPS <i>New</i>	40.00	✓
26	2 PCS "L" PLATE <i>New</i>	70.00	✓

3389.10
2541.82

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000236
Date: 30 Oct 2020
Veh Reg No: SMN7418E
Make/Model: TOYOTA VIOS 1.5 E (AUTO)
Chasis No: MR2B23F3701180375
Reg. Date: 27/08/2019
Your Ref No: GBG3933C

Claim Type: Third Party
Accident Date: 30/10/2020
TP Veh Reg No: GBG3933C

Estimate Repair Cost to Vehicle No :SMN7418E

Quantity	Description	List Price	Amount
		SS	SS
27	1 SET REAR BUMPER STICKER <i>Not in</i>	280.00 200	
28	1 SET BOOTLID TRIM CLIPS <i>Not in</i>	40.00 +	
29	1 PC BOOT LID NUMBER "638" STICKER <i>Not in</i>	35.00 /	
30	1 PC REAR NUMBER PLATE <i>Not in</i>	50.00 +	
31	1 SET REAR PANEL TRIM CLIPS <i>Not in</i>	40.00 10	
32	1 SET REAR FENDER TRIM CLIPS LH <i>Not in</i>	40.00 +	
33	1 PC REAR FENDER STICKER <i>Not in</i>	280.00 +	
		875.00	875.00
	Labour		
34	1 TO CHECK WIRING	50.00 50	
35	1 TO REPLACE STICKERS	160.00 80	
36	1 TO SPRAY UNDERSEAL	120.00 40	
37	1 (REAR) TO SPRAY PAINTING	1,000.00 700	
38	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 700	
39	1 TO REMOVE AND REFIT INNER TRIM	120.00 60	
		2,450.00	2,450.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/s 30/10/20
OS hrs.

total: 450682
C/s: 3.6K.

3.6K