

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 1 Nov 2020

ASSESSMENT FOR REPAIR: HONDA XADV750 - FBN8844G

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
		\$385.00 /scr
1 pc	Front mudguard	\$1,388.00 ?
1 pc	Front left fork assy	\$1,388.00 ?
1 pc	Front right fork assy	\$485.00 ?
1 pc	Steering stem	\$90.00 ?
2 pcs	Steering stem bearing @ \$45.00	\$188.00 XSVL
1 pc	Front wheel axle	\$460.00 XSVL
1 pc	Front brake disk left	\$460.00 XSVL
1 pc	Front brake disk right	\$450.00 /MIS
1 pc	Front windshield	\$40.00 ?
4 pcs	Windshield nut @ \$10.00	\$40.00 ?
4 pcs	Windshield screw @ \$10.00	\$280.00 ?
2 pcs	Front windshield cover @ \$140.00	\$75.00 /MIS
1 pc	Head light protector	\$185.00 /MIS
1 pc	Left side wind deflector	\$550.00 /scr
1 pc	Left side fairing assy upper	\$245.00 /scr
1 pc	Left side fairing black cover	\$395.00 /scr
1 pc	Left side crash bar	\$305.00 ?
1 pc	Steering handle	\$214.00 /scr
1 pc	Left handguard	\$485.00 /scr
1 pc	Left rear cover	\$485.00 /scr
1 pc	Rear mudguard assy	\$145.00 /DEF.
1 pc	Rear number plate lamp	
		<hr/>
		\$5,002.00
	Less discount 10%	\$500.20
		<hr/>
		\$4,501.80
	<u>Special nett items</u>	
1 pc	Front sport rim	\$485.00 X SVL
1 pc	Box rack	\$255.00 X SVL
1 pc	Rear number plate	\$30.00 /BT
1)	Towing charges	\$120.00 X
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$800.00 300
	To replace and balance front wheel	
3)	rim	\$150.00 X NN

- | | | |
|----|--|-------------------------|
| 4) | To knock, straighten chassis & body
balancing | \$380.00 XNN |
| 5) | To remove/refit, replace (if damage) check and
straighten front fork tubes. | \$180.00 ? |
| 6) | Decals full wrap | \$500.00 250 |

Total Estimate

\$7,401.80

10,764.20#

Note: The above estimate is subjected to the prevailing GST of 7%

NAZ LKK
3/11/2020 1400
LIS

2 D Ays

CHECK ITEM PHOTO

AFTER REPAIR PHOTO

For Bike Production Pte Ltd



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: