

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 02/11/2020

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LAW HAI KOON (LIU HAIKUN)

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10426305R00

Accident Date : 04/10/2020

Vehicle No : SMP-3203-Z

Make & Model : HONDA FIT 1.3GF CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR DOOR RH <i>bt</i> ✓	1,015.00	
1	REAR DOOR FRAME STICKER RH (SET)(BLACK) <i>re</i> ✓	52.00	
1	REAR FENDER RH <i>repair</i>	1,085.00	
1	REAR FENDER INNER SHIELD RH X NN	121.10	
6	REAR FENDER INNER SHIELD CLIPS X NN	30.00	
	Sub Total	2303.10	
	Add 15% On Parts	460.62	
<u>Special Nett Item</u>			
1	REPAIR - REAR SPORT RIM RH X Repair	150.00	

Date : 02/11/2020

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LAW HAI KOON (LIU HAIKUN)

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10426305R00

Accident Date : 04/10/2020

Vehicle No : SMP-3203-Z

Make & Model : HONDA FIT 1.3GF CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	150.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	700.00	350
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	X
	TO SPRAY PAINT ON AFFECTED AREAS	600.00	400
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	/
	TO TRANSFER ALL REAR RH DOOR FITTING	100.00	60
	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS, GARNISH, CARPET, FLOOR MATS & SEAT	150.00	60
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL	NN 100.00	X

Date : 02/11/2020

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LAW HAI KOON (LIU HAIKUN)

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10426305R00

Accident Date : 04/10/2020

Vehicle No : SMP-3203-Z

Make & Model : HONDA FIT 1.3GF CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

ALIGNMENT

Sub Total

1725.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

4 days / Lumpsum

SUB TOTAL 4,638.72

GST 7.0 % 324.71

TOTAL 4,963.43

Surveyor's name: Rasu - Hy 90010068

Principal's name: LAW HAI KOON (LIU HAIKUN)

Survey Date & Time: 12/11/2020 @ 1020