ASS. REC. BY: THEFT: CS CTI 200	11917/R13 1 SIST
ASSI	GNMENT
From: Date:	Veh No: SMP 32037 Yr Regn: 2019 / 868
Eslimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
DD ATP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No: SMP 3263-Z	Make: HONDA FIT 1-3 GF CVT . C.C 1317
at Workshop m/s ETU622	Colour GREY A/C: Insured / Std / NI / NA
30, BUKIT BATOX CRESCENT	Sp.Reading 0(1837 T/Radio: Insured / Std / NI / NA
nsured: CT'	Eng/No:
olicy No.	C/No: 4K33417782
laims No.	Gen. Cond: Good / Falr Poor / Burnt
um Insured: . Excess:	Steering: Norder Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205 50R 6
(Policy Condition)	R: C
Remark; The veh had commenced its N/S O/S	BOLDUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
al. or Market Value: 67K	Fron! Rear
AC Accident Rport: Consistent? : Yes or No	R/Bal. & mm R/Bal. & mm
·····	UBal. b mm UBal. b mm
	D.O.A. 84 66 2020 D.O.I. 12 (1) 2020
	Survey held at ETY02
um Sum: % · 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OL	1. 01.04
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
9/02/2021 5.48pm Spoken to Rakeswaran, vehicle h	nas not send in for repair due to liability 50/50.
1/03/2021 Submit preli report (preli fig \$2,137.05)	
Note: The vehicle has not send in for rep	pair.
,	
YE .	
	* · · · · · · · · · · · · · · · · · · ·
ale/Time, File Pass to? : Prell. Report	Days Of Repair: 4
Y Tom Kopole	
: Final Report	Resurvey No. of Trip: Survey Fee:
ate/Time, File Return to?	Transportation:
Add	Fee: : Site Insp (\$)s+Rssi
	: Interview (\$) Photos
pp Format: TP	: Tech, Invs (\$) Others
LE.F. \$2,137.05	:Weelend (%
42,101.00	Constitution of the second of
	· YOTAL

in .