



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJG6666J

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AIG ASIA PACIFIC INSURANCE PTE. LTD.

ACCIDENT DATE : 20/10/2020

TP VEH REG NO : SJG6666J

## ESTIMATE

NO : QUOT202011-000002(00)

DATE : 02/11/2020

POLICY NO : 999995730

VEH REG NO : SMJ1623P

MAKE/MODEL : B.M.W. 216I GRAN TOURER

CHASSIS NO : WBA6V12080ED05747

ENGINE NO : 43195499B38A15A

REG. DATE : 2019

## Estimate Repair Cost to Vehicle No : SMJ1623P

| Description                                                                                                                                      | Quantity | Unit Price<br>S\$ | Amount<br>S\$       |
|--------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------------|---------------------|
| <b>LIST PRICE</b>                                                                                                                                |          |                   |                     |
| 1 Headlamp assy - RH                                                                                                                             | 1        | 2,495.75          | 2,495.75 ✓          |
| 2 Front bumper                                                                                                                                   | 1        | 997.25            | 997.25 X            |
| 3 Front bumper side retainer - RH                                                                                                                | 1        | 115.25            | 115.25 X            |
| 4 Front bumper fog lamp cover - RH                                                                                                               | 1        | 143.65            | 143.65 ✓            |
| 5 Front bumper sensor seals                                                                                                                      | 4        | 12.00             | 48.00 ?             |
| 6 Front bumper clips                                                                                                                             | 15       | 9.00              | 135.00 X            |
|                                                                                                                                                  |          |                   | 3,934.90            |
|                                                                                                                                                  |          | Less 10%          | 393.47              |
|                                                                                                                                                  |          |                   | 3,541.43            |
| <b>LABOUR</b>                                                                                                                                    |          |                   |                     |
| 7 To remove and refit front bumper sensor and check wiring system                                                                                | 1        | 100.00            | 100.00 X            |
| 8 To pabel beat LH front fender, LH front bumper bracket, including replacement of parts and align where necessary, to refit and adjust the same | 1        | 800.00            | 800.00 200l         |
| 9 To putty and spray paint on affected areas                                                                                                     | 1        | 800.00            | 800.00 240l         |
| 10 To reset and re-programme headlamp fault code                                                                                                 | 1        | 350.00            | 350.00 X ?          |
|                                                                                                                                                  |          |                   | 2,050.00            |
| <b>TOTAL</b>                                                                                                                                     |          |                   | <b>S\$ 5,591.43</b> |
| <b>ADD GST @ 7%</b>                                                                                                                              |          |                   | <b>391.40</b>       |
| <b>GRAND TOTAL</b>                                                                                                                               |          |                   | <b>S\$ 5,982.83</b> |

SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED EIGHTY-TWO AND CENTS EIGHTY-THREE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE