

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0826/2020/NS
DATE : 02-Nov-20
WIP : 56207

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

3 days - ok - Jy - 01 Feb 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAN JUN XIAN SHAWN
ADDRESS : BLK 620 BUKIT PANJANG RING ROAD
#15-822
SINGAPORE 670620
TELEPHONE : HP +65 97894220
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149949
VEHICLE NO : **SMV 8306 X**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TFS
MODEL YEAR : 22/10/2020
ENGINE NO : CZE 866338
CHASSIS NO : WAUZZZ8V8LA088972
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Oct-20
PLACE OF ACCIDENT : CAR PARK BUKIT BATOK EAST AVE 6

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 8306 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE ARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATUE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGAMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$	2,152.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 8306 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 1,842.00	\$ 1,473.60
2	FRONT BUMPER FIXING PARTS		\$ 185.00	
3	FRONT BUMPER GUIDE SECTION - LH		\$ 38.00	\$ 30.16
4	FRONT BUMPER GRILLE - CENTRE		\$ 159.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 293.00	\$ 234.40
6	FRONT BUMPER CLOSING ELEMENT - LH		\$ 293.00	
7	RADIATOR GRILLE		\$ 1,406.00	\$ 1,124.80
8	RADIATOR GRILLE CLOSING ELEMENT		\$ 189.00	
9	AIRCON STICKER	NEC	\$ 8.00	\$ 5.68
10	CAUTION SIGN STICKER	NEC	\$ 14.00	\$ 10.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 186.00	
12	FRONT REINFORCEMENT BEAM		\$ 715.00	
13	FRONT BUMPER FOAM FILLER PIECE		\$ 187.00	
14	FOAM FILLER PIECE COVER		\$ 121.00	
15	SIGNAL HORN - LH HIGH TONE		\$ 197.00	
16	FRONT FENDER - LH		\$ 841.00	
17	FRONT FENDER ATTACHMENT PARTS		\$ 71.00	
18	FRONT FENDER BRACKET - LH		\$ 47.00	
19	FRONT FENDER BRACE		\$ 95.00	
20	FRONT FENDER CLOSING ELEMENT - LH		\$ 61.00	
SUB TOTAL SPARE PARTS		:	\$ 6,948.00	\$ 2,879.44

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 8306 X

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
	<i>c/f</i>		\$	2,879.44
21	WHEEL HOUSING LINER - LH	\$	167.00	\$ 133.20
22	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	57.00	
23	LED HEADLIGHT - LH	\$	5,455.00	
24	LIFT CYLINDER - LH	\$	141.00	
25	LIFT CYLINDER HOSE	\$	67.00	
26	WASH WATER RESERVOIR	\$	202.00	
27	WASH WATER RESERVOIR PUMP	\$	151.00	
28	RADIATOR AIR GUIDE - LH	\$	24.00	\$ 19.20
29	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
31	SUNDRIES	\$	200.00	\$ 30.16
TOTAL SPARE PARTS		:	\$ 13,472.00	\$ 3,122.00
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$ 2,152.00
GRAND TOTAL		:	\$ 18,474.00	\$ 5,274.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.