

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJS 5896E
 TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877
 TEL: 65073848
 ATTN: Motor Claim Department

FAX: 65073849

Estimate No: ES2090876/WS
 Date: 02 Nov 2020
 Policy No: 5110539659-01
 Veh Reg No: SJS5896E
 Make/Model: TOYOTA TOYOTA
 CAMRY 2.0 AUTO ABS
 AIRBAG
 Chassis No: MR053BK4107047724
 Engine No: 1AZE144553
 Reg. Date: 25/08/2009

WS Ref: TP/FC
 Claim Type: Third Party
 Accident Date: 30/10/2020
 TP Veh Reg No: SHA6980G

Not Authorized

11 Pay @

Perjury After Paint

3-4 days

Estimate Repair Cost to Vehicle No :SJS5896E

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price	530.20	1 PC	530.20	
1 REAR BUMPER	420.90	1 PC	420.90	
2 REAR BUMPER REINFORCEMENT	3.50	6 PC	21.00	
3 REAR BUMPER CLIPS	602.00	1 PC	602.00	
4 REAR PANEL			1,574.10	
	Less 25%		393.53	1,180.58
Special Net	200.00	1 PC	200.00	
5 1SET REVERSE SENSOR			200.00	200.00
Labour	700.00	1 LA	700.00	
6 PANEL BEATING	700.00	1 LA	700.00	
7 PUTTY AND SPRAY PAINTING.	60.00	1 LA	60.00	
8 REMOVE,REFIT & STRAIGHTEN REAR EXHAUST AND CHECK LEAKING.	30.00	1 LA	30.00	
9 RUSTPROOFING			1,490.00	1,490.00
			Total	S\$ 2,870.58
			Add GST @ 7%	200.94
			Total Amount Payable	S\$ 3,071.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE