

AUBURN AUTO PTE LTD
UEN : 200805305G
176 Sin Ming Drive Autocare #04-18, Singapore 575721
Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Hyundai
Avante

Vehicle Number : SJT5465K

Quantity	Description	Repairer's Estimate
FRONT		
1	Front Number Plate MIS	\$50 20 ✓
1	Front bumper Tow Cover NN	\$30 ✗
1	Headlight bracket NN	\$20 ✗
1	Front number plate base garnish BR	\$200 20 ✓
1	Fog light Cover NN	\$170 ✗
1	Engine undercover NN	\$110 ✗
1	Front Grill BR	\$420 382 ✓
1	Front Driving Sensor NN	\$450 ✗
1	Right Side Headlamp Bracket NN	\$450 ✗
1	Left Chasis Garnish NN	\$500 ✗
1	Right Chasis Garnish NN	\$500 ✗
1	Left Side Headlight NN	\$750 ✗
1	Right Side Headlight CUT	\$750 450 ✓
1	Front bumper bracket NN	\$35 ✗
1	Front Bumper Retainer BR	\$500 80 ✓
1	Front Right Hand Fender DD	\$850 436 ✓
1	Front Support NN	\$300 ✗
1	Front Reinforcement Bar BT	\$600 366 ✓
1	Front Bumper DD	\$1,100 445 ✓
1	BONNET NN	\$1,300 ✗
SIDE		
1	Bumper Strip (Bumper lower grille) BR	\$200 122 ✓
1	Right Side Fender NN	\$250 ✗
1	Right Mirror NN	\$350 ✗
1	Under Tray Cover (front panel lower deflector) BR	\$350 60 ✓
1	Rim tyre NN	\$360 ✗
1	Right Headlight NN	\$400 ✗
1	Condenser NN	\$450 ✗
1	Radiator NN	\$450 ✗
1	Reinforcement Bar Sponge BR	\$450 145 ✓
1	Right Side Mirror NN	\$1,200 ✗
1	Front Right Door Replace NN	\$2,000 ✗
BACK		
1	REAR NUMBER PLATE BRACKET NN	\$150 ✗
1	REAR NUMBER PLATE NN	\$50 ✗
1	REVERSE SENSOR Shorted	\$200 ✓ Nett
1	REAR NUMER PLATE LAMP NN	\$250 ✗
1	MISSING SCREWS & NUTS NEC	\$350 60 ✓
1	RIGHT TAIL LIGHT BRACKET NN	\$500 ✗
1	REAR END PANEL INNER GARNISH NN	\$250 ✗
1	TAIL LAMP LOWER BRACKET NN	\$80 ✗
1	REAR RIGHT BUMPER RETAINER NN	\$500 ✗
1	REAR RIGHT TAILLIGHT BRACKET NN	\$80 ✗
1	REAR LEFT TAILLIGHT BRACKET NN	\$80 ✗
1	REAR RIGHT DOOR BODY LINING NN	\$300 ✗
1	REAR RIGHT RIMS AND TYRE NN	\$800 ✗
1	REAR RIGHT WHEEL BEARING NN	\$800 ✗
1	REAR LEFT WHEEL BEARING NN	\$800 ✗
1	REAR RIGHT DOOR BODY LINING NN	\$800 ✗
1	SPARE TYRE BOARD NN	\$800 ✗
1	REAR CUSHION SEAT LOCK NN	\$800 ✗
1	BOOTLID WEATHERSTRIP NN	\$1,000 ✗
1	FAULTY WIRING NN	\$1,200 ✗
1	REAR RIGHT BOOT MUDGUARD NN	\$1,200 ✗
1	REAR LEFT BOOT MUDGUARD NN	\$1,200 ✗
1	BUMPER BRACKET NN	\$1,200 ✗
1	REAR RIGHT ABSORBER NN	\$1,200 ✗
1	REAR LEFT ABSORBER NN	\$1,200 ✗
1	REAR RIGHT MUDGUARD NN	\$1,200 ✗
1	REAR LEFT MUDGUARD NN	\$1,200 ✗
1	LEFT BOOTLID LAMP NN	\$1,200 ✗
1	RIGHT BOOTLID LAMP NN	\$1,200 ✗
1	LEFT TAIL LIGHT NN	\$380 ✗
1	RIGHT TAIL LIGHT NN	\$380 ✗
1	BOOT LOCK NN	\$85 ✗
1	REAR UNDERCARRIAGE NN	\$1,500 ✗
1	BOOT LID NN	\$750 ✗
1	SPARE TYRE WELL NN	\$1,500 ✗
1	BOOT INTERIOR LINING NN	\$2,000 ✗
1	REAR BUMPER DD	\$750 486 ✓
1	REAR BUMPER CENTRE BRACKET NN	\$75 ✗
1	REAR END PANEL Repair	\$550 ✗
1	REAR BUMPER SIDE RETAINERS BR	\$95 ✓
1	REAR SPARE TYRE PANEL NN	\$650 ✗
1	REAR SPARE TYRE BOARD NN	\$250 ✗
1	REAR EXHAUST SILENCER MOUNTINGS NN	\$70 ✗
LABOUR & MISC		
	Checking of wiring, lighting and resetting	\$500 30 ✓
	Remove and refit rear undercarriage	\$500 ✗
	Wheel alignment	\$300 ✗
	Remove and replace damaged parts	\$1,000 ✗
	Apply undercoating on repaired and replaced panel	\$800 30 ✓
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200 600 ✓
	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000 700 ✓
Total Repair Cost :		\$50,470

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To identify damaged parts during recovery
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Steve (LKK)
Without Prejudice
3/11/20
L/S
Resurvey After Spray
4 repair days