

ASS. REC. BY: AmuREF: CC3/Alh 20011947/R1ba3

4909

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 77212at Workshop m/s Volkswagenof 17, TUNAS AVE 9Insured: ALG

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 51K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC 77212 Yr Regn: 20/6 / MAYType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN GOLF 1.2 TS AT c.c. 1197Colour Blue A/C: Insured / Std / NI / NASp. Reading 84462 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZANZAW 126576

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16R: 62

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 01/11/2020Survey held at 17, TUNAS AVE 9Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 03/11/2020

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit 18K

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Repair Format: _____

Lump Sum / L&R (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/3

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
CHO
TUCK LUEN
16 ANG MO KIO CENTRAL 3
#13-27
Singapore 567748

Document no.
Document date 02-11-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020029075/ 1
Job order date 02-11-2020
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLC7721Z	5G12BZ	25-05-2016	VWVZZZAUZGW126576	Golf 1.2 TLBM 81 TSI D7F	84,462

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Leaked Check, Vacuum & Regas	1	pcs.	420.00	#1	420.00	449.40
	A/C GAS	1	pcs.	60.00	#1	60.00	64.20
5G6827025AA	Heckklappe 3/4 X Svc	1	pcs.	2,004.17	#1	2,004.17	2,144.46
	REAR LID						
5G0945087B	Additional Brake Light Wi 3 X Svc	1	pcs.	158.79	#1	158.79	169.91
	3 RD BRAKELIGHT						
510827861A	Wasserablaufschlauch 3 MP	1	pcs.	11.40	#1	11.40	12.20
	WATER DRAINAGE HOSE						
5G6827705E	Gasket 3 X Svc	1	pcs.	260.93	#1	260.93	279.20
	REAR WETHERSTRIP						
5G6971829B	Grommet X n n	2	pcs.	14.67	#1	29.34	31.39
D 169300M2	1k Window Adhesive X n n	2	pcs.	49.51	#1	99.02	105.95
D 00940104	All Purpose Cleaner X n n	1	pcs.	89.22	#1	89.22	95.47
D 00920002	Primer X n n	1	pcs.	25.74	#1	25.74	27.54
D 181802M1	Activator For Precoated W X n n	1	pcs.	23.77	#1	23.77	25.43
D 00950025	Applicator X n n	2	pcs.	9.39	#1	18.78	20.09
5G0853687 2ZZ	Inscription Bright Chrome 3 n n	1	pcs.	77.15	#1	77.15	82.55
	LOGO - GOLF						
5G0853675APCW	Inscription Pure White/Po 3 n n	1	pcs.	77.56	#1	77.56	82.99
B	LOGO - BLUEMOTION						
5G0853675 2ZZ	Inscription Bright Chrome 3 n n	1	pcs.	69.85	#1	69.85	74.74
	LOGO - TSI						
5G6807417APGRU	Cover For Bumper Primed de	1	pcs.	1,165.55	#1	1,165.55	1,247.14
5G6807568B 9B9	Rear Diffusor Satin Black 3 n n	1	pcs.	323.62	#1	323.62	346.27
	SPOILER						
WHT005263	Rivet	6	pcs.	1.09	#1	6.54	7.00
5G0807305D	Bumper 3 ? 61	1	pcs.	619.61	#1	619.61	662.98
	REINFORCEMENT						
5G6807863C	Attachment Strip 3 ? cm	1	pcs.	64.97	#1	64.97	69.52
	REAR BUMPER CTR BRACKET						
5G6807393A	Guide Piece 3 ? cm	1	pcs.	37.46	#1	37.46	40.08
	LHR BUMPER BRACKET (UPPER)						
5G6807394A	Guide Piece 3 ? X Svc	1	pcs.	37.46	#1	37.46	40.08
	RHR BUMPER BRACKET (UPPER)						
5G6807393	Guide Piece 3 ? X Svc	1	pcs.	37.46	#1	37.46	40.08
	LHR BUMPER BRACKET (SIDE)						
5G6807394	Guide Piece 3 ? X Svc	1	pcs.	37.46	#1	37.46	40.08
	RHR BUMPER BRACKET (SIDE)						
1K8943021	License Plate Light 3 X Svc	2	pcs.	38.01	#1	76.02	81.34
8K0973702	Flat Contact Housing With 3 ? X Svc	1	pcs.	10.35	#1	20.70	22.15
	NUMBER PLATE LIGHT WIRE HOUSING						
5G0945105	Reflector 3 X Svc	1	pcs.	71.19	#1	71.19	76.17
	LH						

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/3

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
CHO
TUCK LUEN
16 ANG MO KIO CENTRAL 3
#13-27
Singapore 567748

Document no.
Document date 02-11-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020029075/ 1
Job order date 02-11-2020
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLC7721Z	5G12BZ	25-05-2016	VWWZZZAUZGW126576	Golf 1.2 TLBM 81 TSI D7F	84,462

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5G0945106	Reflector <i>?? xsu</i> RH	1	pcs.	71.19	#1	71.19	76.17
5G6813309	End Plate END PANEL OUTER <i>?? repair</i>	1	pcs.	121.41	#1	121.41	129.91
D 007500A2	Zinc Spray <i>?? xsu</i>	1	pcs.	62.88	#1	62.88	67.28
D 180003M2	2k-Body Adhesive <i>?? xsu</i>	1	pcs.	406.76	#1	406.76	435.23
D 476KD1M2	Sealant Can Be Sprayed <i>?? xsu</i>	1	pcs.	61.67	#1	61.67	65.99
N 91017602	Weld Stud <i>?? xsu</i>	6	pcs.	0.88	#1	5.28	5.65
5Q0825701E	Heat Shield For Exhaust M <i>bt</i>	1	pcs.	142.50	#1 <i>99.75</i>	142.50	152.48
5G6253609K	Exhaust Silencer Rear <i>xsu</i>	1	pcs.	1,009.60	#1	1,009.60	1,080.27
1K0253141R	Dual Clamp <i>xsu</i>	1	pcs.	57.56	#1 <i>40.29</i>	57.56	61.59
5G0823031J	Hood FRT BONNET <i>?? repair</i>	1	pcs.	1,131.64	#1	1,131.64	1,210.85
5G1823509D	Hood Latch <i>?? xsu</i> BONNET LOCK	1	pcs.	255.59	#1	255.59	273.48
5G2823531D	Cable Hood Latch <i>?? xsu</i> LOCK CABLE	1	pcs.	33.99	#1	33.99	36.37
5G0807217BNGRU	Cover For Bumper Primed <i>?? de</i> FRT BUMPER	1	pcs.	1,158.63	#1 <i>811.04</i>	1,158.63	1,239.73
5G0807723D	Support Part <i>?? xsu</i> BUMPER INNER BRACKET LH	1	pcs.	54.69	#1	54.69	58.52
5G0807724D	Support Part <i>?? xsu</i> BUMPER INNER BRACKET RH	1	pcs.	54.69	#1	54.69	58.52
5G0807049A	Guide Piece <i>?? xsu</i> BUMPER SIDE BRACKET LH	1	pcs.	20.91	#1	20.91	22.37
5G0807050A	Guide Piece <i>?? xsu</i> BUMPER SIDE BRACKET RH	1	pcs.	20.91	#1	20.91	22.37
5G0807248F	Foam Insert <i>?? cm</i>	1	pcs.	41.99	#1 <i>29.39</i>	41.99	44.93
5G0807109AL	Impact Beam <i>?? bt</i> FRT REINFORCEMENT	1	pcs.	619.61	#1 <i>433.73</i>	619.61	662.98
5G0853651G ZLL	Radiator Grille Satin Bla <i>cm</i>	1	pcs.	472.52	#1 <i>330.76</i>	472.52	505.60
5G2941005E	Twin Halogen Headlamps <i>?? xsu</i> H/LAMP LH	1	pcs.	725.37	#1	725.37	776.15
5G2941006E	Twin Halogen Headlamps <i>?? xsu</i> H/LAMP RH	1	pcs.	725.37	#1 <i>507.76</i>	725.37	776.15
6R0973735	Flat Contact Housing <i>?? xsu</i> H/LAMP WIRE HOUSING	2	pcs.	19.19	#1	38.38	41.07
5G0805588AC	Lock Carrier With Mountin <i>?? xsu</i>	1	pcs.	1,144.12	#1	1,144.12	1,224.21
5G0805567	Support For Lock Carrier <i>?? cm</i>	1	pcs.	43.22	#1 <i>30.25</i>	43.22	46.25
5G0805705G	Guide <i>?? cm</i> FRT BUMPER CTR BRACKET	1	pcs.	39.74	#1 <i>27.82</i>	39.74	42.52
5G0805931	Cross Support <i>?? bt</i> H/LAMP TOP PANEL LH	1	pcs.	36.06	#1 <i>25.24</i>	36.06	38.58
5G0805932	Cross Support <i>?? bt</i> H/LAMP TOP PANEL RH	1	pcs.	36.06	#1 <i>25.24</i>	36.06	38.58
G 12E050A2	COOLANT <i>?? xsu</i>	2	pcs.	20.88	#1	41.76	44.68
	LABOUR FRT	6	pcs.	840.00	#1 <i>1680</i>	5,040.00	5,392.80

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 3/3

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
CHO
TUCK LUEN
16 ANG MO KIO CENTRAL 3
#13-27
Singapore 567748

Document no.
Document date 02-11-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020029075/ 1
Job order date 02-11-2020
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLC7721Z	5G12BZ	25-05-2016	WVWZZZAUZGW126576	Golf 1.2 TLBM 81 TSI D7F	84,462

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	SPRAT PAINT FRT	4	pcs.	800.00	#1 1600	3,200.00	3,424.00
	LABOUR REAR	8	pcs.	840.00	#1 3360	6,720.00	7,190.40
	SPRAY PAINT REAR	6	pcs.	800.00	#1 3200	4,800.00	5,136.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#1 420	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1 420	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REVERSE SENSOR	1	pcs.	400.00	#1 XSVL	400.00	428.00
	FRT NUMBER PLATE	1	pcs.	80.00	#1 SCL	80.00	85.60
	REAR NUMBER PLATE	1	pcs.	80.00	#1 MSL	80.00	85.60
	R&R REAR EXHAUST PIPE	1	pcs.	840.00	#1 420	840.00	898.80
	AIG DIRECT SETTLEMENT						
	DOA : 01/11/2020						
	TP VEH : SDZ3001T						
	SURVEY BY :						

Quotation valid till 09-11-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,240.00	37,907.86	7%	2,740.35	39,147.86	41,888.21
Total	1,240.00	37,907.86		2,740.35	39,147.86	41,888.21

Customer

Rasul
Hp 90010068
14 days + 1 = 15 days
03/11/2020 @ 1530
Service Advisor
Resurvey before paint

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify
the Repairer of the following.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: