

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SDJ2277E [YOUR INSURED] & SJH707J [OUR CLIENT]
ON 30/10/2020.

ESTIMATED REPAIR COSTS FOR SJH707J

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE 44	\$ 985.00	X
1PC	TAILGATE LOCK 44	\$ 289.00	X
1PC	TAILGATE INNER TRIM 44	\$ 486.50	X
1PC	TAILGATE WINDSCREEN MOULDING 44	\$ 110.00	X
1PC	TAILGATE 'HONDA' LOGO 44	\$ 85.00	X
1PC	TAILGATE 'FIT' EMBLEM 44	\$ 82.00	X
1PC	REAR BUMPER 44	\$ 758.00	X
2PC	REAR BUMPER SIDE RETAINER L+R @ \$46.00 EACH 44	\$ 92.00	X
1PC	REAR BUMPER TOW HOOK COVER 44	\$ 28.30	X
2PC	TAIL LAMP L+R @ \$598.20 EACH 44	\$ 1,196.40	X
2PC	TAIL LAMP PANEL L+R @ \$485.30 EACH 44	\$ 970.60	X
1PC	REAR END PANEL 44	\$ 498.60	X
1PC	REAR END PANEL TOP GARNISH 44	\$ 298.20	X
2PC	REAR FENDER L+R @ \$1,329.80 EACH 44	\$ 2,659.60	X
2PC	REAR FENDER INNER TRIM L+R @ \$342.90 EACH 44	\$ 685.80	X
1PC	SPARE WHEEL PANEL 44	\$ 893.40	X
1PC	SPARE WHEEL PANEL TOP BOARD 44	\$ 699.20	X
2PC	SPARE WHEEL QUARTER PANEL L+R @ \$499.20 EACH 44	\$ 998.40	X
1PC	SPARE WHEEL PANEL TOOL BOX 44	\$ 389.50	X

PARTS SUM: \$ 12,205.50

PARTS LESS 20%: \$ 2,441.10

PARTS TOTAL: \$ 9,764.40

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE 44	\$ 40.00	X
*	TO SUPPLY 1 SET REAR REVERSE SENSOR 44	\$ 300.00	X

*	TO SUPPLY REAR END PANEL SEALANT HL	\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT HL	\$ 80.00	X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS HL	\$ 50.00	X
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS HL	\$ 50.00	X
*	TO SUPPLY REAR WINDSCREEN SEALANT HL	\$ 80.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE HL REPAIRS	\$ 300.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,000.00 300/-	
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,000.00 300/-	
*	TO TUFF COAT DAMAGED AREAS HL	\$ 300.00	X
*	TO RNR REVERSE CAMERA HL	\$ 100.00	X
*	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD HL	\$ 250.00	X
*	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD HL	\$ 200.00	X
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS HL	\$ 250.00	X
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS HL	\$ 200.00	X
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET HL ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	X
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD HL	\$ 120.00	X

LABOUR & S/N TOTAL: \$ 4,700.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 14,464.40

03/11/2020 e 1700h

N/A Authn

Part by Part.

Tan

LKK Auto



2 days

? / P 600/-

2 days

Photo after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: