



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD C/O: LOW YEAP TOH & GOON LLP 20 MAXWELL ROAD #12-01 MAXWELL HOUSESINGAPORE 069113			Ref: CS/LAW20011961/Atf3e2 Date: 10/03/2021 Code: INC3	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	FBK 9911E	Veh. Inspected	SMD 9330M	
Policy No.		Coverage (\$)	0.00	
Claim No.	GEP 2482 07 20	Excess (\$)	0.00	
Assign From	SITI MARINA	Assign Date	02/11/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI Q2	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZGA0JA084734	Colour	GREY	
Odometer	51889 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	MICHELIN	6 mm	
L/H Front Tyre	215/55 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/02/2019	Inspection Date	11/11/2020	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	