



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP Budget Direct.
Keron.

JIA FOOD LOGISTICS PTE LTD
60 KAKI BUKIT PLACE #02-12
SINGAPORE 415979

Contact : 94716633, 84446633

ESTIMATE

Repair Code : CLM16518

Date in : 02/11/2020

Vehicle Num. : GBD5769M

Model : CITROEN DISPATCH 2.0I HDI AT

Chassis/Eng# : VF7XURHHAEZ011595/10WAPH0400705

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Defend</i>	1	800.77	✓ 800.77
REAR BUMPER REFLECTOR L/R <i>LH cancelled</i>	2	100.22	100.22 200.44
REAR BUMPER REINFORCEMENT <i>Best</i>	1	600.22	✓ 600.22
REAR END PANEL <i>Rejis</i>	1	900.33	+ 900.33
REAR TAILGATE 'C&C' EMBLEM	1	120.11	+ 120.11
REAR TAILGATE 'CITROEN' EMBLEM	1	122.33	+ 122.33
REAR TAILGATE 'DISPATCH' EMBLEM	1	144.22	+ 144.22
REAR TAILGATE 'LOGO' EMBLEM	1	100.33	+ 100.33
REAR TAILGATE WEATHER STRIP	1	300.77	+ 300.77
Subtotal before discount			3,289.52
Percentage discount 10%			328.95
Sub-total 1			2,960.57
REAR BUMPER REVERSE SENSOR <i>Dangd</i>	1	250.00	200 250.00
REAR TAILGATE '70KM' STICKER <i>NHL per</i>	1	30.00	+ 30.00
Subtotal before discount			280.00
Percentage discount 0%			0.00
Sub-total 2			280.00
Parts-total			3,240.57

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

JIA FOOD LOGISTICS PTE LTD

60 KAKI BUKIT PLACE #02-12

SINGAPORE 415979

Contact : 94716633, 84446633

ESTIMATE

Repair Code : CLM16518

Date in : 02/11/2020

Vehicle Num. : GBD5769M

Model : CITROEN DISPATCH 2.0I HDI AT

Chassis/Eng# : VF7XURHHAEZ011595/10WAPH0400705

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

✓ 80.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

✗ 800.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

280

200 - 700.00

Labour Total

1,580.00

Parts & Labour Total

4,820.57

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
4/s 03/11/20
02 days
total: 1831.08
4/s: 1.4K