

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms : AIG Asia Pacific Insurance Pte Ltd

Date: 2/11/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLQ374P

CHASSIS NO : JTDKB3FU103560655

MAKE / MODEL : Toyota Pirus 1.8 Hybrid

DATE OF ACCIDENT : 30/10/2020

YOUR INSURED VEHICLE NUMBER : SLV6312C

MILEAGE : 158144 Km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	F/R fender / pb	1PC	\$ 933.10	\$ 933.10	/
2	F/R fender inner liner X SVC	1PC	\$ 49.70	\$ 49.70	/
3	F/L fender Hybrid emblem X SVC	1PC	\$ 52.30	\$ 52.30	X
4	F/R fender Hybrid emblem X NEC	1PC	\$ 52.30	\$ 52.30	/
5	F/R headlamp ? / CRA	1PC	\$ 2,530.10	\$ 2,530.10	/
6	Front bumper / CRU	1PC	\$ 495.50	\$ 495.50	/
LIST TOTAL S\$:				\$ 4,113.00	4,010.50
25.00% DISCOUNT S\$:				\$ 1,028.25	-25%
				\$ 3,084.75	3,007.88

SPECIAL NETT

1	Bumper and fender liner clips	NEC	1 SET	\$ 200.00	30.
Special Nett Total S\$:				\$ 200.00	30

LABOUR CHARGES

1	To labour charge for removing F/R fender, front bumper out to facilitate replacement of damaged parts	\$ 900.00	500
---	---	-----------	-----

2	To respray front bumper and F/R fender	\$ 800.00	1400
LABOUR TOTAL S\$:		\$ 1,700.00	
TOTAL S\$:		\$ 4,984.75	900
7% GST		\$ 348.93	
GRAND TOTAL S\$:		\$ 5,333.68	900

Repair dg - 3 days

LIS

After paint photo

Sun Pin (Lte).

02/11/2020.

TP without prejudice.

3,007.88
30
900
3,937.88
-20%
3,150.30

LIS
\$ 3,150
3 days