



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

| | | | | | |
|-------------------------|---|---------------------------|----------------|---------------------|----------------------------|
| Customer | : CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 | Document No. | : SQT20003550 | Page | 1 |
| Registration No | : SLV6353J | Date | : 31. Oct 2020 | Customer No. | : WZC008 |
| Chassis No | : MRHFC5650HT000796 | Svc Advisor | : YOU PO SOON | Engine No | : R16B22001228 |
| Model | : CIVIC 1.6 VTI YM2017 | Engine No | : R16B22001228 | Date Time | : 31. Oct 2020 10:48:36 AM |
| Owner's Name | : WANG MING HWEE | Surveyor Name | : | Survey Date | : |
| Ins Policy No. | : | Authorisation Date | : | | |
| Date of Accident | : 30/10/2020 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|---|-----|-------------------|--------|----------------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: WANG MING HWEE OWNER INSURER: NTUC INCOME INS. ACC DATE: 30/10/2020 SURVEYED BY: DATE: REF NO: TP INSURER: C/TAIPING INS. TP VEH: SLX9638H | | | | | | |
| 71500-TEC-Q00ZZ | FACE ASSY,RR.BUMPER <i>20/02</i> | 1 | 617.20 ✓ | 5 | 586.34 ✓ | 41.04 | 627.38 |
| 71530-TEA-T00ZZ | BEAM COMPRR.BUMPER <i>R</i> | 1 | 180.00 X | 5 | 171.00 X | 11.97 | 182.97 |
| 71502-TEX-Y00 | GARNISH,RR.BUMPER LOWER <i>ground</i> | 1 | 39.80 ✓ | 5 | 37.81 ✓ | 2.65 | 40.46 |
| 71593-TEA-T01 | SPACERR.RR.BUMPER SIDE <i>17</i> | 1 | 11.50 X | 5 | 10.92 X | 0.76 | 11.68 |
| 71598-TEA-T01 | SPACERL.RR.BUMPER SIDE <i>17</i> | 1 | 11.50 X | 5 | 10.92 X | 0.76 | 11.68 |
| 91505-TM8-003 | CLIP,BUMPER <i>neu</i> | 7 | 2.30 ✓ | 5 | 15.29 ✓ | 1.07 | 16.36 |
| 75722-TBA-A00 | EMBLEM SETRR. <i>neu</i> | 1 | 12.90 ✓ | 5 | 12.25 ✓ | 0.86 | 13.11 |
| 75725-TEA-T01 | EMBLEMRR. <i>neu</i> | 1 | 12.00 ✓ | 5 | 11.40 ✓ | 0.80 | 12.20 |
| 75701-TBA-A10 | EMBLEM,H-MARK <i>neu</i> | 1 | 13.30 ✓ | 5 | 12.63 ✓ | 0.88 | 13.51 |
| 90301-ST0-003 | NUTPUSH 3MM <i>17</i> | 2 | 2.10 X | 5 | 3.99 X | 0.28 | 4.27 |
| 38387-TZ5-A01 | ANTENNA ASSYL.F. <i>17</i> | 1 | 60.80 X | 5 | 57.76 X | 4.04 | 61.80 |
| 74940-SZW-003 | BUZZER ASSYSMART <i>17</i> | 1 | 62.90 X | 5 | 59.75 X | 4.18 | 63.93 |
| 74851-TEA-003 | LOCK ASSYTRUNK <i>17</i> | 1 | 81.20 X | 5 | 77.14 X | 5.40 | 82.54 |
| 39680-TEX-Y41ZT | SENSOR ASSY,PARKING <i>5VC</i> | 2 | 148.40 X | 5 | 281.96 X | 19.74 | 301.70 |
| | | | Sum Item | | 1349.16 | 94.43 | 1,443.59 |
| BOSUN | SUNDRIES <i>neu</i> | 1 | 50.00 <i>20</i> | | 50.00 | 3.50 | 53.50 |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | 1 | 150.00 <i>120</i> | | 150.00 | 10.50 | 160.50 |
| BA02R | REMOVE & INSTALL REVERSE SENSORS-4 PCS (N) | 1 | 180.00 <i>150</i> | | 180.00 | 12.60 | 192.60 |

Printed on 31/10/2020 10:55:27 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|---|---------------------|----------------------------|---------------------------|----------------|
| Customer | : CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 | Document No. | : SQT20003550 | Page | 2 |
| Registration No | : SLV6353J | Date | : 31. Oct 2020 | Customer No. | : WZC008 |
| Chassis No | : MRHFC5650HT000796 | Svc Advisor | : YOU PO SOON | Engine No | : R16B22001228 |
| Model | : CIVIC 1.6 VTI YM2017 | Date Time | : 31. Oct 2020 10:48:36 AM | Surveyor Name | : |
| Owner's Name | : WANG MING HWEE | Survey Date | : | Authorisation Date | : |
| Ins Policy No. | : | | | | |
| Date of Accident | : 30/10/2020 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|------------------|---|-----|------------|--------|----------------|---------------|------------------|
| BC012R | RESET VEHICLE SMART ENTRY SYSTEM | 1 | 450.00 | X | 450.00 | 31.50 | 481.50 |
| BKRP02S | STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS. <i>650</i> | 1 | 1500.00 | 975 | 1500.00 | 105.00 | 1605.00 |
| BP03R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) <i>520</i> | 1 | 1700.00 | 1040 | 1700.00 | 119.00 | 1819.00 |
| Sum Labor | | | | | 4030.00 | 282.10 | 4,312.10 |

Survey By: Marcus Lkh
 Date & Time: 9/11/20 @ 9.30
 Excess: ---
 Status: not Authorized
 Signature: Tan photo refer painting
4 days.

Total Amount 5,379.16 376.53 5,755.69
Total (Inclusive of GST) 5,755.69

LKK Auto Consultants hence notify the Repairer of the following:

- To be done before/after spray painting
- To do damaged parts during resurvey
- Work to be done subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No third party survey allowed
- Surveyor's report must be approved by insurance company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 31/10/2020 10:55:27 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.