

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

2/1/2020
Attn: Marcus

WD: 4 Day

Page 1/1

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0079569 / CHINA TAIPING
 Chassis No: MRHFC5650HT000796
 License No: SLV6353J
 Mileage: 39703
 Engine No: R16B22001228

Document No: SVO20059071
 Printed By: PSYOU
 Order Date: 9. November 2020
 Order Time: 9:30:32 AM
 Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO: 75341) OWNER: WANG MING HWEE OWNER INSURER: NTUC INCOME INS. ACC DATE: 30/10/2020 SURVEYED BY: MARCUS CHUA DATE: REF NO: TP INSURER: C/TAIPING INS. TP VEH: SLX9638H						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	5	586.34	41.04	627.38
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	39.80	5	37.81	2.65	40.46
91505-TM8-003	CLIP,BUMPER	7	2.30	5	15.29	1.07	16.36
75722-TBA-A00	EMBLEM SETRR.	1	12.90	5	12.25	0.86	13.11
75725-TEA-T01	EMBLEMRR.	1	12.00	5	11.40	0.80	12.20
75701-TBA-A10	EMBLEM,H-MARK	1	13.30	5	12.63	0.88	13.51
	SUM PARTS:				675.72	47.30	723.02
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	120.00		120.00	8.40	128.40
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R	EXT-YJ	1	150.00		150.00	10.50	160.50
	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)						
BKRP02S	EXT-YJ	1	975.00		975.00	68.25	1,043.25
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
BP03R	EXT-YBH	1	1,040.00		1,040.00	72.80	1,112.80
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
	SUM LABOUR:				2,305.00	161.35	2,466.35
	TOTAL SGD				2,980.72	208.65	3,189.37
	Total Payable (SGD)						3,189.37

GST Amount is calculated from individual line(s)