

ASS. REC. BY:

REF:

C72 / 200119661Kc

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

1-B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKQ 11954

Yr Regn:

11, 14

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Lexus

ES 250

c.c

2494

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

89977

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTHB JIGG 0020 63394

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/10/20

D.O.I.

3/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

191 O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/3 84306.06 Cabins (Red. 155, 32.7)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trlp:

1

Survey Fee:

Transportation:

S + RS SI

Fines

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / (B.I.) (\$

4,306.06

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Seow Ah Tee
 Period of Insurance : 03 Nov 2019 To 02 Nov 2020
 Engine No. : 2ARE905076
 Chassis No. : JTHBJ1GG602063394

Vehicle No. : SKQ1195U
 Policy No. : 2100390636-05
 Endorsement No. :
 Issued Date : 07 Oct 2019

ABOUT THE COVER

Make/Model : LEXUS ES250

Engine Capacity/Tonnage : 2,494.00 CC

Driver Restriction : NA

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2014

Insuring with COE/PAF : Yes

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Seow Ah Tee - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

1002644418/AC4

0030211000

AIG ASIA PACIFIC INSURANCE PL
 78 SHENTON WAY #07-16 AIG BUILDING
 SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSCZSS

78 Shenton Way #07-16 AIG Building S079120 | T +65 6419 3000 | www.aig.sg

AIG Asia Pacific Insurance Pte. Ltd.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 438H

Vehicle Details

Vehicle No.: SKQ1195U
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Oct 2020
Vehicle Make: TOYOTA
Vehicle Model: LEXUS ES250 AUTO
Primary Colour: Grey
Manufacturing Year: 2014
Engine No.: 2ARE905076
Chassis No.: JTHBJ1GG602063394
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$34,805.00
Original Registration Date: 03 Nov 2014
First Registration Date: 03 Nov 2014
Transfer Count: 0
Actual ARF Paid: \$40,727.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Nov 2024
PARF Rebate Amount: \$28,508.00

Intended COE Rebate Details

COE Expiry Date: 02 Nov 2024
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$72,990.00
COE Rebate Amount: \$29,256.00
Total Rebate Amount: \$57,764.00

The information contained herein is correct as at 30 Oct 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2020 15:42
Date Of Accident	29/10/2020 22:00
Exact Location Of Accident	TOH TUCK CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ1195U
Insured/Policyholder	
Name Of Registered Owner	SEOW AH TEE
NRIC No	SXXXX438H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92266158
Alternative Phone No	OTHERS-92266158

Vehicle Particulars

Manufacturer	LEXUS
Model	ES250
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100390636-05
Cover Note Number	

Driver

Name of Driver	SEOW AH TEE
NRIC No	SXXXX438H
Date Of Birth	30/06/1951
Occupation	INDOOR
Date Of Driving Pass	30/06/1973
Driving Experience	47 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92266158
Fax Number	
Contact Number	OTHERS-92266158
Email Address	NOEMAIL

Address	4 TOH TUCK CLOSE
Postcode	596971
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBG4D
Vehicle Make/Model/Colour	BMW 520I
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH SIN CHUAN
NRIC/Passport Number	
Contact Number	97361983
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

30 OCT 2020

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.:

SKETCH PLAN



A-SBG 4D

B-SRQ 1195U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident happened on 29/10/2020 at around 10 pm.

I was stationary at the junction of Toh Tuck Crescent waiting for the traffic to clear. While waiting, a car no. SBG 4D turning from Toh Tuck Road into Toh Tuck Crescent, drove too close to me and hit onto the right front portion of my car. No one was injured.

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 30 OCT 2020

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature]

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: SKQ1195U
Repairer Reference: 71674
Date calculated: 02/11/2020 2:06 PM

Full Report
Registration: SKQ1195U
Printed: 02/11/2020 2:06 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	SKQ1195U	Date of Incident:	29/10/20
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: LEXUS
Model: ES (V6)
Sub Model: 250
Model Sheet Number: 24 23 30
Registration: SKQ1195U
VIN number:
Odometer:

Model Specs

FROM 07/2015 XENON HEADLAMPS

PARK PILOT SYSTEM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notified
Repair by paint
5 days

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: FRT BUMPER , RADIATOR GRILLE, PARK SENSOR AND REQUIRED ATTACHED PARTS REMOVE AND REFIT		23.0	96.60
NO NUMBER	R + R FRONT BUMPER DAMPER		1.0	4.20
B040)	ADJUST HEADLAMPS		3.0	12.60
8100141	RENEW R/HEADLAMP (FRONT BUMPER REMOVED) INCLUDES: HEADLAMP R + R NOT INCLUDED: ADJUST HEADLAMPS		7.0	29.40
B110	RENEW R/FRT WING (FRONT BUMPER, RIGHT HEADLAMP ASSY AND R/SILL MOULDING REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R.		5.0	21.00
B100	R + R RIGHT SILL MOULDING		4.0	16.80
B070	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW		6.0	25.20
851091)	R + R WASHER RESERVOIR		8.0	33.60
672191	R + R R/F OUTER DOOR HANDLE		1.0	4.20
752051	R + R R/MIRROR INCLUDES: DOOR TRIMS REMOVE AND REFIT		5.0	21.00
NO NUMBER	R + R LOWER FRONT BUMPER COVER		1.0	4.20
NO NUMBER	R + R R/ENGINE COVER		2.0	8.40
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		6.60	66.0	277.20
Total of Labour				277.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	BONNET NEW PART PAINTING		24.0	
	R/F WING NEW PART PAINTING		10.0	
	FRONT BUMPER NEW PART PAINT K1R		11.0	
	L/F CTR PARK AID SEN SURFACE PAINT PLAST.		3.0	
	R/F CTR PARK AID SEN SURFACE PAINT PLAST.		3.0	
	L/F OUT PARK AID SEN SURFACE PAINT PLAST.		3.0	
	L/F WING SURFACE PAINT		5.0	
	RIGHT FRONT DOOR SURFACE PAINT		7.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	67.30
0742	R/F WING NEW PART PAINTING	16.12
0283	FRONT BUMPER NEW PART PAINT K1R	43.63
0267	L/F CTR PARK AID SEN SURFACE PAINT PLAST.	0.26

Paint Material Per Part

Code	Description	Price SGD
0268	R/F CTR PARK AID SEN SURFACE PAINT PLAST.	0.26
0269	L/F OUT PARK AID SEN SURFACE PAINT PLAST.	0.26
0741	L/F WING SURFACE PAINT	7.04
1482	RIGHT FRONT DOOR SURFACE PAINT	15.49

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			66.0	
Preparation Main Work Metal		0.80	8.0	33.60
Preparation Comp. Work Plastic		0.30	3.0	12.60
Total	10 WU/h	7.70	77.0	323.40

Material Cost - Paint

	Price SGD
New Part Painting	83.42
New Part Painting - Plastic K1R	43.63
Surface-/Blend Paint	22.53
Surface Painting Plastic	0.78
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	177.46

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0471	BONNET	53301 33160	Original	R ₁	750.00 ✓
0415	CTR BUMPER GRILLE	53112 33150	Original	n ₁	90.00 ✓
0283	FRONT BUMPER	52119 3T910	Original	T ₁	380.00 ✓
0344	FRONT BUMPER DAMPING	52611 33280	Original	CM	65.00 ✓
0260	FRT NO PLATE BRKT	52114 33450	Original	R ₁	45.00 ✓
0410	GRILLE	53111 33450	Original	CM	360.00 ✓
0431	GRILLE BADGE	90975 02125		^	0.00 ✓
0420	GRILLE MOULDING	53121 33090	Original	CM	110.00 ✓
0303	R/F BUMPER COVER	52128 33210	Original	mir	10.00 ✓
0270	R/F OUT PARK AID SEN	89341 78010C1	Original	su	155.00 X
0742	R/F WING	53811 33230	Original	Bu	330.00 ✓
0842	R/WHEELHOUSE SHELL	53875 33220	Original	CM	125.00 ✓
0840	R/W-HOUSE SUPPORT	53851 33050	Original	mis	25.00 2
0534	RIGHT BONNET STOP	90541 15033	Original	CM	8.00 ✓
0562	RIGHT HEADLAMP ASSY	81145 33C40	Original	Bu	1,000.00 ✓
1436	WASHER CONTAINER	85315 33461	Original	n ₁	95.00 ✓
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				3,548.00
u: Used parts	Fixed Sundry Parts Price				100.00
	Total				3,648.00

Extras

Code	Description	Price SGD
1001	FRONT NUMBER PLATE	<i>B1</i> 35.00* ✓
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	3,548.00	
Total Parts	100.00	3,648.00
Labour Time Base 10 WU/h		
Total 66.0 WU X 42.00 SGD/h	277.20	
Total of Labour		277.20
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 77.0 WU X 42.00 SGD/h	323.40	
Material Cost	177.46	
Total Paint Including Material		500.86
Repair Cost Excludes GST		4,461.06
GST (+7.0%)		312.27
Repair Cost Included GST		4,773.33

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Kenneth Kong (LKKAUTO)

From: Kenneth Kong (LKKAUTO)
Sent: Thursday, 25 March, 2021 9:02 AM
To: Jenny Lim
Subject: RE: Finalisation - SKQ 1195U / Lexus ES250

Final repair cost \$4306.06, 5days confirmed.

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]
Sent: Wednesday, 24 March, 2021 3:05 PM
To: Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: Finalisation - SKQ 1195U / Lexus ES250

Dear Sir

For your confirmation, please:

- Parts: \$3,393.00
- SN: \$35.00
- Sundry: \$100.00
- L&M: \$778.06
- Sub-total: \$4,306.06
- Less XC: -
- Total: \$4,306.06 / 8 days

Supporting documents and photographs are enclosed for your reference.

We look forward to hearing from you soon.

Thank you.

Kind regards
Jenny Lim
Lai Huat (Meng Kee) Motor Pte Ltd
Sin Ming Autocity
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Singapore 575722
Tel: 64538110 Fax: 64596267

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: SKQ1195U
Repairer Reference: 71674
Date calculated: 24/03/2021 1:36 PM

Full Report
Registration: SKQ 1195U
Printed: 24/03/2021 1:36 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	SKQ1195U	Date of Incident:	29/10/20
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	LEXUS
Model:	ES (V6)
Sub Model:	250
Model Sheet Number:	24 23 30
Registration:	SKQ 1195U
VIN number:	
Odometer:	

Model Specs

FROM 07.2015	XENON HEADLAMPS	PARK PILOT SYSTEM
--------------	-----------------	-------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: FRT BUMPER , RADIATOR GRILLE, PARK SENSOR AND REQUIRED ATTACHED PARTS REMOVE AND REFIT		23.0	96.60
NO NUMBER	R + R FRONT BUMPER DAMPER		1.0	4.20
B040)	ADJUST HEADLAMPS		3.0	12.60
8100141	RENEW R/HEADLAMP (FRONT BUMPER REMOVED) INCLUDES: HEADLAMP R + R NOT INCLUDED: ADJUST HEADLAMPS		7.0	29.40
B110	RENEW R/FRT WING (FRONT BUMPER, RIGHT HEADLAMP ASSY AND R/SILL MOULDING REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R.		5.0	21.00
B100	R + R RIGHT SILL MOULDING		4.0	16.80
B070	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW		6.0	25.20
851091)	R + R WASHER RESERVOIR		8.0	33.60
672191	R + R R/F OUTER DOOR HANDLE		1.0	4.20
752051	R + R R/MIRROR INCLUDES: DOOR TRIMS REMOVE AND REFIT		5.0	21.00
NO NUMBER	R + R LOWER FRONT BUMPER COVER		1.0	4.20
NO NUMBER	R + R R/ENGINE COVER		2.0	8.40
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		6.60	66.0	277.20
Total of Labour				277.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	BONNET NEW PART PAINTING		24.0	
	R/F WING NEW PART PAINTING		10.0	
	FRONT BUMPER NEW PART PAINT K1R		11.0	
	L/F CTR PARK AID SEN SURFACE PAINT PLAST.		3.0	
	R/F CTR PARK AID SEN SURFACE PAINT PLAST.		3.0	
	L/F OUT PARK AID SEN SURFACE PAINT PLAST.		3.0	
	L/F WING SURFACE PAINT		5.0	
	RIGHT FRONT DOOR SURFACE PAINT		7.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	67.30
0742	R/F WING NEW PART PAINTING	16.12
0283	FRONT BUMPER NEW PART PAINT K1R	43.63
0267	L/F CTR PARK AID SEN SURFACE PAINT PLAST.	0.26

Paint Material Per Part

Code	Description	Price SGD
0268	R/F CTR PARK AID SEN SURFACE PAINT PLAST.	0.26
0269	L/F OUT PARK AID SEN SURFACE PAINT PLAST.	0.26
0741	L/F WING SURFACE PAINT	7.04
1482	RIGHT FRONT DOOR SURFACE PAINT	15.49

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		66.0	
Preparation Main Work Metal	0.80	8.0	33.60
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	77.0	323.40

Material Cost - Paint

	Price SGD
New Part Painting	83.42
New Part Painting - Plastic K1R	43.63
Surface-/Blend Paint	22.53
Surface Painting Plastic	0.78
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	177.46

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Part Source	Price SGD
0471	BONNET	53301 33160	Original	750.00
0415	CTR BUMPER GRILLE	53112 33150	Original	90.00
0283	FRONT BUMPER	52119 3T910	Original	380.00
0344	FRONT BUMPER	52611 33280	Original	65.00
	DAMPING			
0260	FRT NO PLATE BRKT	52114 33450	Original	45.00
0410	GRILLE	53111 33450	Original	360.00
0431	GRILLE BADGE	90975 02125		0.00
0420	GRILLE MOULDING	53121 33090	Original	110.00
0303	R/F BUMPER COVER	52128 33210	Original	10.00
0742	R/F WING	53811 33230	Original	330.00
0842	R/WHEELHOUSE SHELL	53875 33220	Original	125.00
0840	R/W-HOUSE SUPPORT	53851 33050	Original	25.00
0534	RIGHT BONNET STOP	90541 15033	Original	8.00
0562	RIGHT HEADLAMP ASSY	81145 33C40	Original	1,000.00
1436	WASHER CONTAINER	85315 33461	Original	95.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,393.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			3,493.00

Extras

Code	Description	Price SGD
1001	FRONT NUMBER PLATE	35.00*
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts	3,393.00	
Fixed Sundry Parts Price	100.00	
Total Parts		3,493.00
Labour Time Base 10 WU/h		
Total 66.0 WU X 42.00 SGD/h	277.20	
Total of Labour		277.20
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 77.0 WU X 42.00 SGD/h	323.40	
Material Cost	177.46	
Total Paint Including Material		500.86
Repair Cost Excludes GST		4,306.06
GST (+7.0%)		301.42
Repair Cost Included GST		4,607.48

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.