



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------------|----------------------------|----------------|
| AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | | Ref: CS/AGI20011967/Dcd3n2 | |
| | | | Date: 22/04/2021 | |
| | | | Code: AGI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SKB 5373A | Veh. Inspected | SHC 2123E |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | C10007806 | Excess (\$) | 0.00 |
| | Assign From | IVY RATILLA | Assign Date | 03/11/2020 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | HYUNDAI I40 | c.c | 1685 |
| | Engine No. | HIDDEN | Year of Reg. | 2017 |
| | Chassis No. | KMHLB41UMHU100087 | Colour | BLUE |
| | Odometer | 402453 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 205/60 R16 | DURATURN | 5 mm |
| | L/H Front Tyre | 205/60 R16 | DURATURN | 5 mm |
| | R/H Rear Tyre | 205/60 R16 | DURATURN | 5 mm |
| | L/H Rear Tyre | 205/60 R16 | DURATURN | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 30/10/2020 | Inspection Date | 04/11/2020 |
| | Survey held at | BLK 9 SECTOR C #01-42 | | |
| | Repairer | BIFROST AUTO PTE LTD | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 9 Working Days | |