

ASS. REC. BY:

REF:

A6/200119801Ky

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBJ 7174J Yr Regn: 07, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer Sprinter 316CDi 2143

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

17.613

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WOB 9076332P 092397

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

Continental 235/65R16

R: 7040

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

30/10/20

D.O.I.

3/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

151 N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Quotation Details - Quotation No SN-002012-20-20015

Date
Created: 3/11/2020

Customer Details:

Fedex
Federal Express (s) Pte Ltd
90 Alps Ave
Singapore 498746
Fax: 69222550

Vehicle Details

Vehicle No : GBJ 7174 J
Vehicle Make : MERCEDES
Vehicle Model : SPRINTER 2019
Vehicle Engine No :
Engine Chassis No :
Mileage :

Owner's Accident Details

Job No : SN-002012-20-20015
JobCategory : OD - Parts By Parts
Date of Accident :
Owner's Insurer :
Location of Accident :

Surveyor's Details

Surveyor Name :
Surveyor Company :
Surveyor ContactNo :
Surveyor FaxNo :
Quotation Submission Date :
Surveyor Approve Date :
Supplementary Date :
Supplementary Approve Date :

View Photo Accident Photo

Not Authorized
Person B4 point

FM
[Signature]

6 days

Kenneth
HP. 96910663

KennethKang@kkauto.com

Item No	Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev Qty	Rev Unit Price	Remarks	Final Total Price	Surveyor Approval
Materials												
1	1	Bonnet Assy	1	\$1,145.00	-10.00	\$1,030.50	\$1,030.50	0	0	RM	\$0.00	✓
2	2	Bonnet Hinge RH	1	\$91.00	-10.00	\$81.90	\$81.90	0	0	RM	\$0.00	X
3	3	Bonnet Hinge LH	1	\$91.00	-10.00	\$81.90	\$81.90	0	0	RM	\$0.00	X
4	4	Bonnet Lock	1	\$148.00	-10.00	\$133.20	\$133.20	0	0	RM	\$0.00	X
5	5	Bonner Cable	1	\$54.00	-10.00	\$48.60	\$48.60	0	0	RM	\$0.00	X
6	6	Headlamp LH	1	\$2,750.00	-10.00	\$2,475.00	\$2,475.00	0	0	RM	\$0.00	✓
7	7	Headlamp RH	1	\$2,750.00	-10.00	\$2,475.00	\$2,475.00	0	0	RM	\$0.00	X
8	8	Front Grille	1	\$980.00	-10.00	\$882.00	\$882.00	0	0	RM	\$0.00	✓
9	9	Front Bumper Retainer	1	\$38.00	-10.00	\$34.20	\$34.20	0	0	RM	\$0.00	X
10	10	Front Bumper Retainer RH	1	\$38.00	-10.00	\$34.20	\$34.20	0	0	RM	\$0.00	✓
11	11	Front Bumper LH	1	\$981.00	-10.00	\$882.90	\$882.90	0	0	RM	\$0.00	✓
12	12	Front Support Panel	1	\$360.00	-10.00	\$324.00	\$324.00	0	0	CM	\$0.00	✓
13	13	Front Bumper Centre Garnish	1	\$110.00	-10.00	\$99.00	\$99.00	0	0	CM	\$0.00	✓
14	14	Support Panel LH	1	\$93.00	-10.00	\$83.70	\$83.70	0	0	CM	\$0.00	✓
15	15	Support Panel Centre	1	\$65.00	-10.00	\$58.50	\$58.50	0	0	CM	\$0.00	✓
16	16	Front Fender Inner Shield Clips	10	\$7.50	-10.00	\$6.75	\$67.50	0	0	CM	\$0.00	✓
17	17	Front Windscreen Glass	1	\$2,200.00	-10.00	\$1,980.00	\$1,980.00	0	0	CM	\$0.00	✓
18	18	Radiator Assy	1	\$966.00	-10.00	\$869.40	\$869.40	0	0	CM	\$0.00	✓
19	19	Radiator Fan Cowling	1	\$181.00	-10.00	\$162.90	\$162.90	0	0	CM	\$0.00	✓
20	20	Radiator Fan Motor	1	\$499.00	-10.00	\$449.10	\$449.10	0	0	RM	\$0.00	X
21	21	Air Con Motor	1	\$369.00	-10.00	\$332.10	\$332.10	0	0	RM	\$0.00	✓
22	22	A/C Condenser Assy	1	\$1,283.00	-10.00	\$1,154.70	\$1,154.70	0	0	RM	\$0.00	X
23	23	Radiator Lower Pipe LH	1	\$153.00	-10.00	\$137.70	\$137.70	0	0	RM	\$0.00	X
24	24	Horn	1	\$176.00	-10.00	\$158.40	\$158.40	0	0	RM	\$0.00	✓
25	25	Air Filter Box	1	\$420.00	-10.00	\$378.00	\$378.00	0	0	RM	\$0.00	✓
26	26	Auto Oil Cooler	1	\$971.00	-10.00	\$873.90	\$873.90	0	0	RM	\$0.00	✓
27	27	Wiper Tank	1	\$112.00	-10.00	\$100.80	\$100.80	0	0	RM	\$0.00	X
28	28	Intercooler Assy	1	\$880.00	-10.00	\$792.00	\$792.00	0	0	RM	\$0.00	✓

29	29	Airbag Control Switch	1	\$1,054.00	-10.00	\$948.60	\$948.60	0	0	<i>Sm</i>	\$0.00	<u>X</u>
30	30	Wheel House	1	\$550.00	-10.00	\$495.00	\$495.00	0	0	<i>n</i>	\$0.00	<u>X</u>
31	31	Front Fender LH	1	\$560.00	-10.00	\$504.00	\$504.00	0	0	<i>Sm</i>	\$0.00	<u>✓</u>
32	32	Intercooler Lower Garnish	1	\$49.00	-10.00	\$44.10	\$44.10	0	0		\$0.00	<u>?</u>
33	33	A/C Fan Cowling	1	\$80.00	-10.00	\$72.00	\$72.00	0	0	<i>CM</i>	\$0.00	<u>2</u>

Material Total: \$18,244.80 Final Sub-Total : \$0.00

Special Nett Items

1	34	Coolant 8L	1	\$168.00	0.00	\$168.00	\$168.00	0	0	<i>me</i>	\$0.00	<u>5000</u>
2	35	Auto Oil 4L	1	\$108.00	0.00	\$108.00	\$108.00	0	0		\$0.00	<u>?</u>
3	36	Fedex Decal	1	\$160.00	0.00	\$160.00	\$160.00	0	0		\$0.00	<u>?</u>
4	37	Top Up Gas	1	\$80.00	0.00	\$80.00	\$80.00	0	0		\$0.00	<u>✓</u>
5	38	Towing Fee	1	\$180.00	0.00	\$180.00	\$180.00	0	0	<i>(Bill)</i>	\$0.00	<u>?</u>

Special Nett Items Total: \$696.00 Final Sub-Total : \$0.00

Labour

1	39	R&R Front Windscreen	1	\$180.00	0.00	\$180.00	\$180.00	0	0		\$0.00	<u>1200</u>
2	40	R&R Radiator, Condenser & Intercooler	1	\$160.00	0.00	\$160.00	\$160.00	0	0		\$0.00	<u>1000</u>
3	41	Straighten & Panel Beat Accident Area	1	\$800.00	0.00	\$800.00	\$800.00	0	0		\$0.00	<u>6000</u>
4	42	Respray Bonnet, Bonnet Inner, Front Fender RH, Front Fender LH, Wheel House	1	\$900.00	0.00	\$900.00	\$900.00	0	0		\$0.00	<u>6000</u>
5	43	R&R Bonnet Sticker	1	\$40.00	0.00	\$40.00	\$40.00	0	0	<i>Inland?</i>	\$0.00	<u>?</u>

Labour Total: \$2,080.00 Final Sub-Total : \$0.00

Others

Others Total: \$0.00 Final Sub-Total : \$0.00

Total Price: \$21,020.80 Final Total Price : \$0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/11/2020 13:46
Date Of Accident 30/10/2020 16:25
Exact Location Of Accident UBI ROAD 3
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ7174J
Insured/Policyholder
Name Of Registered Owner FEDERAL EXPRESS (SINGAPORE) PTE LTD
Co Reg No 1XXXXX740W
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-69222929

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model SPRINTER 316CDI/3665 AUTO ABS
Exact Purpose for which vehicle was being used at time of accident DELIVERY AND PICK-UP
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number 100878963
Cover Note Number

Driver

Name of Driver ASRIZAM BIN AS ARI
Passport No/FIN GXXXX819M
Date Of Birth 01/04/1984
Occupation OUTDOOR
Date Of Driving Pass 06/06/2017
Driving Experience 3 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97742784
Fax Number
Contact Number
Email Address NOEMAIL

Address 90 ALPS AVE
 Postcode 498746
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON OCT 30 @16:25HRS I WAS AT THE TRAFFIC LIGHT JUNCTION OF UBI ROAD 3. I STOPPED BEHIND A LORRY WITH VEHICLE PLATE GBJ6757J. WHEN THE LEFT TURN TRAFFIC LIGHT TURNED GREEN, THE LORRY IN FRONT OF ME JAMMED BRAKED AND ROLLED BACKWARD A BIT. I JAMMED BRAKE TO AVOID HITTING THE LORRY, BUT IT WAS TOO LATE, STILL HIT THE LORRY BEHIND LEFT. MY VAN FRONT LEFT DENTED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ6757J
 Vehicle Make/Model/Colour TOYOTA DYNA/SILVER
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver SONNY TAN @WOO SIN
 NRIC/Passport Number SXXXX100B
 Contact Number 97561944
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN

Veh A = GBJ 7174 J
Veh B = GBJ 6757 J



Ubi Road 3

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Oct 30 @ 16:25hrs I was at the traffic light junction of Ubi Road 3. I stopped behind a lorry with vehicle plate GBJ 6757 J. When the left turn traffic light turned green, the lorry in front of me jammed brake and rolled backward a bit. I jammed brake to avoid hitting the lorry, but it was too late, still hit the lorry behind left. My van front left dented.

DECLARATION

I/We hereby declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: