

Quotation Details - Quotation No SN-002012-20-20015

Date
Created: 3/11/2020

Customer Details:

Fedex
Federal Express (s) Pte Ltd
90 Alps Ave
Singapore 498746
Fax: 69222550

Vehicle Details


Vehicle No : GBJ 7174 J
Vehicle Make : MERCEDES
Vehicle Model : SPRINTER 2019
Vehicle Engine No :
Engine Chassis No :
Mileage :

Owner's Accident Details

Job No : SN-002012-20-20015
Job Category : OD - Parts By Parts
Date of Accident :
Owner's Insurer :
Location of Accident :

Surveyor's Details

Surveyor Name :
Surveyor Company :
Surveyor Contact No :
Surveyor Fax No :
Quotation Submission Date :
Surveyor Approve Date :
Supplementary Date :
Supplementary Approve Date :



View Photo Accident Photo

Not Authorized
Murray B4 point

FM
[Signature]

delay

Kennerh
HP. 96910663

KennerhKenje1kkauto.com

Item No	Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev Qty	Rev Unit Price	Remarks	Final Total Price	Surveyor Approval
Materials												
1	1	Bonnet Assy	1	\$1,145.00	-10.00	\$1,030.50	\$1,030.50	0	0	M	\$0.00	✓
2	2	Bonnet Hinge RH	1	\$91.00	-10.00	\$81.90	\$81.90	0	0	R	\$0.00	X
3	3	Bonnet Hinge LH	1	\$91.00	-10.00	\$81.90	\$81.90	0	0		\$0.00	✓
4	4	Bonnet Lock	1	\$148.00	-10.00	\$133.20	\$133.20	0	0	R	\$0.00	X
5	5	Bonner Cable	1	\$54.00	-10.00	\$48.60	\$48.60	0	0	cm	\$0.00	✓
6	6	Headlamp LH	1	\$2,750.00	-10.00	\$2,475.00	\$2,475.00	0	0	cm	\$0.00	✓
7	7	Headlamp RH	1	\$2,750.00	-10.00	\$2,475.00	\$2,475.00	0	0	cm	\$0.00	✓
8	8	Front Grille	1	\$980.00	-10.00	\$882.00	\$882.00	0	0	cm	\$0.00	✓
9	9	Front Bumper Retainer RH	1	\$38.00	-10.00	\$34.20	\$34.20	0	0	cm	\$0.00	X
10	10	Front Bumper Retainer LH	1	\$38.00	-10.00	\$34.20	\$34.20	0	0	cm	\$0.00	✓
11	11	Front Bumper	1	\$981.00	-10.00	\$882.90	\$882.90	0	0	cm	\$0.00	✓
12	12	Front Support Panel	1	\$360.00	-10.00	\$324.00	\$324.00	0	0	cm	\$0.00	✓
13	13	Front Bumper Centre Garnish	1	\$110.00	-10.00	\$99.00	\$99.00	0	0		\$0.00	✓
14	14	Support Panel LH	1	\$93.00	-10.00	\$83.70	\$83.70	0	0		\$0.00	✓
15	15	Support Panel Centre	1	\$65.00	-10.00	\$58.50	\$58.50	0	0	cm	\$0.00	✓
16	16	Front Fender Inner Shield Clips	10	\$7.50	-10.00	\$6.75	\$67.50	0	0	cm	\$0.00	✓
17	17	Front Windscreen Glass	1	\$2,200.00	-10.00	\$1,980.00	\$1,980.00	0	0	cm	\$0.00	✓
18	18	Radiator Assy	1	\$966.00	-10.00	\$869.40	\$869.40	0	0		\$0.00	✓
19	19	Radiator Fan Cowling	1	\$181.00	-10.00	\$162.90	\$162.90	0	0		\$0.00	✓
20	20	Radiator Fan Motor	1	\$499.00	-10.00	\$449.10	\$449.10	0	0		\$0.00	✓
21	21	Air Con Motor	1	\$369.00	-10.00	\$332.10	\$332.10	0	0		\$0.00	✓
22	22	A/C Condenser Assy	1	\$1,283.00	-10.00	\$1,154.70	\$1,154.70	0	0		\$0.00	✓
23	23	Radiator Lower Pipe LH	1	\$153.00	-10.00	\$137.70	\$137.70	0	0	cm	\$0.00	X
24	24	Horn	1	\$176.00	-10.00	\$158.40	\$158.40	0	0	cm	\$0.00	✓
25	25	Air Filter Box	1	\$420.00	-10.00	\$378.00	\$378.00	0	0	cm	\$0.00	✓
26	26	Auto Oil Cooler	1	\$971.00	-10.00	\$873.90	\$873.90	0	0		\$0.00	✓
27	27	Wiper Tank	1	\$112.00	-10.00	\$100.80	\$100.80	0	0	cm	\$0.00	X
28	28	Intercooler Assy	1	\$880.00	-10.00	\$792.00	\$792.00	0	0		\$0.00	✓

29	29	Airbag Control Switch	1	\$1,054.00	-10.00	\$948.60	\$948.60	0	0	<i>sm</i>	\$0.00	<u>X</u>
30	30	Wheel House	1	\$550.00	-10.00	\$495.00	\$495.00	0	0	<i>n</i>	\$0.00	<u>X</u>
31	31	Front Fender LH	1	\$560.00	-10.00	\$504.00	\$504.00	0	0	<i>bu</i>	\$0.00	<u>✓</u>
32	32	Intercooler Lower	1	\$49.00	-10.00	\$44.10	\$44.10	0	0		\$0.00	<u>?</u>
33	33	Garnish A/C Fan Cowling	1	\$80.00	-10.00	\$72.00	\$72.00	0	0	<i>cm</i>	\$0.00	<u>2</u>

Material Total: \$18,244.80 Final Sub-Total : \$0.00

Special Nett Items

1	34	Coolant 8L	1	\$168.00	0.00	\$168.00	\$168.00	0	0	<i>me</i>	\$0.00	<u>501a</u>
2	35	Auto Oil 4L	1	\$108.00	0.00	\$108.00	\$108.00	0	0		\$0.00	<u>?</u>
3	36	Fedex Decal	1	\$160.00	0.00	\$160.00	\$160.00	0	0		\$0.00	<u>?</u> <i>Inland ?</i>
4	37	Top Up Gas	1	\$80.00	0.00	\$80.00	\$80.00	0	0		\$0.00	<u>✓</u>
5	38	Towing Fee	1	\$180.00	0.00	\$180.00	\$180.00	0	0	<i>(Bill)</i>	\$0.00	<u>?</u>

Special Nett Items Total: \$696.00 Final Sub-Total : \$0.00

Labour

1	39	R&R Front Windscreen	1	\$180.00	0.00	\$180.00	\$180.00	0	0		\$0.00	<u>1201</u>
2	40	R&R Radiator, Condenser & Intercooler	1	\$160.00	0.00	\$160.00	\$160.00	0	0		\$0.00	<u>1001</u>
3	41	Straighten & Panel Beat Accident Area	1	\$800.00	0.00	\$800.00	\$800.00	0	0		\$0.00	<u>6001</u>
4	42	Respray Bonnet, Bonnet Inner, Front Fender RH, Front Fender LH, Wheel House	1	\$900.00	0.00	\$900.00	\$900.00	0	0		\$0.00	<u>6001</u>
5	43	R&R Bonnet Sticker	1	\$40.00	0.00	\$40.00	\$40.00	0	0	<i>Inland ?</i>	\$0.00	<u>?</u>

Labour Total: \$2,080.00 Final Sub-Total : \$0.00

Others

Others Total: \$0.00 Final Sub-Total : \$0.00

Total Price: \$21,020.80 Final Total Price : \$0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: