

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 65096584

TO	: AIG	DATE	: 3/11/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: FBN8872A		
VEHICLE MODEL	: YAMAHA MX KING		<i>Cecilia</i>
CHASSIS NO	: MH3UG0710JK276125		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	SIONG / 97864483	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT FENDER <i>cracked</i>	1	\$ 75.00	\$ 75.00
2	FRONT WHEEL SHAFT <i>Bent</i>	1	\$ 45.00	\$ 45.00
3	FRONT FORK ASSY <i>Bent</i>	1	\$ 480.00	\$ 480.00
4	FRONT FORK UNDER BRACKET <i>Bent</i>	1	\$ 185.00	\$ 185.00
5	STEERING CONE AND BEARING <i>new</i>	1	\$ 65.00	\$ 65.00
6	FRONT COWLING <i>cracked</i>	1	\$ 165.00	\$ 165.00
7	FRONT COWLING BASE <i>cracked</i>	1	\$ 155.00	\$ 155.00
8	FRONT LH SIGNAL LAMP <i>Not new</i>	1	\$ 45.00	\$ 45.00
9	HEADLAMP <i>Not new</i>	1	\$ 185.00	\$ 185.00
10	HEADLAMP COVER <i>Not new</i>	1	\$ 55.00	\$ 55.00
11	FRONT FAIRING SIDE (SILVER) <i>cracked</i>	2	\$ 195.00	\$ 370.00
12	YAMAHA LOGO <i>new</i>	2	\$ 20.00	\$ 40.00
13	BALANCER LH <i>ok</i>	1	\$ 35.00	\$ 35.00
14	HANDLE BAR <i>Not new</i>	1	\$ 135.00	\$ 135.00
15	FRONT LH WING MIRROR <i>ok</i>	1	\$ 40.00	\$ 40.00
16	BRAKE LEVER <i>ok</i>	1	\$ 30.00	\$ 30.00
17	FOOT BRAKE LEVER <i>Bent</i>	1	\$ 55.00	\$ 55.00
18	FOOT BRAKE LEVER RUBBER <i>ok</i>	1	\$ 20.00	\$ 20.00
19	FRONT FOOTREST BRACKET <i>Bent</i>	1	\$ 145.00	\$ 145.00
20	ENGINE COVER <i>ok</i>	1	\$ 390.00	\$ 390.00
21	REAR LH FOOTREST <i>Not new</i>	1	\$ 20.00	\$ 20.00
22	REAR LH FOOTREST BRACKET <i>ok</i>	1	\$ 75.00	\$ 75.00
23	REAR LH SIDE FAIRING <i>Not new</i>	1	\$ 190.00	\$ 190.00
24	SWING ARM <i>Not new</i>	1	\$ 380.00	\$ 380.00
TOTAL PRICE:				\$ 3,380.00

75.00
 45.00
 480.00
 185.00
 65.00
 165.00
 155.00
 45.00
 185.00
 55.00
 370.00
 40.00
 35.00
 135.00
 40.00
 30.00
 55.00
 20.00
 145.00
 390.00
 20.00
 75.00
 190.00
 380.00
 320

2300
2070

LESS 10% \$ 338.00
SUB TOTAL PRICE: \$ 3,042.00

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT WHEEL RIM <i>ut</i>	1	\$ 380.00	\$ 380.00
2	FRONT TYRE <i>new</i>	1	\$ 140.00	\$ 140.00
3	FORK OIL <i>for</i>	1 BOT	\$ 40.00	\$ 40.00
4	FORK OIL SEAL	1 SET	\$ 55.00	\$ 55.00
5	STICKERS	1 SET	\$ 100.00	\$ 100.00
		TOTAL :	\$	715.00

395

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	253	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	253	
3	WIRING CHECK	\$ 50.00	30	
4	TOWING FEES	\$ 50.00	✓	

TOTAL: \$ 900.00

580

ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,757.00
TOTAL LABOUR COST: \$ 900.00
TOTAL REPAIR COST: \$ 4,657.00

total: 3045

A/S: 2.4K

04 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: