

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 16 Nov 2020

## **Preliminary Advice**

Insured Vehicle No : SGQ4318K

TP Vehicle No : SLZ1960T

Make : HYUNDAI ELANTRA

Date of Inspection : 09/11/2020

Inspection At : SME MOTOR PTE LTD (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT  
SINGAPORE 417883

Accident Date : 02/11/2020

Assignment Date : 04/11/2020

Est. Duration of Repair : 3

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages REAR portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,678.40
Revised Amount	:S\$	1,487.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,487.60

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : SURVEY ON WP