


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0828/2020/NS
DATE	:	2-Nov-20
WIP	:	55243

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR WONG CHEE WENG
ADDRESS	:	10 BEDOK RESERVOIR VIEW
		#10-31
		SINGAPORE 479236
TELEPHONE	:	HP +65 91891008
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100400305-05
VEHICLE NO	:	SCU 1680 J
MODEL CODE	:	AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR	:	26/1/2015
ENGINE NO	:	C7C 209954
CHASSIS NO	:	WAUZZZ8V2F1044146
MILEAGE	:	107321KM
DATE IN	:	30-Oct-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	30-Oct-20
PLACE OF ACCIDENT	:	MARYMOUNT RD (BTW SING MIN AVE/ UPPER THOMSON RD)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCU 16801

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00 ✓	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 ✓	
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 480.00 ✓ <i>photo.</i>	
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00 ✓ <i>2500.</i>	
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$ 3,800.00 ✓ <i>2200.</i>	
6	TO RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$ 480.00 ✓ <i>? X N N</i>	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 9,712.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCU 1680 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER		\$ 1,847.00	de ✓	1477.60
2 REAR BUMPER FIXING PARTS		\$ 191.00	X nn	
3 REAR BUMPER GUIDE SECTION - LH/RH	25.12 2	✓ \$ LH-cra ✓ 32.00	9 RH X nn	crack
4 REAR BUMPER LOCKING MECHANISM	nn 2	\$ LH-cra ✓ 59.00	RH X nn	
5 REAR BUMPER SPOILER		\$ 234.00	de ✓	187.2
6 REAR LIGHT REFLECTOR - LH/RH	2	\$ 82.00	X nn	
7 LED LICENSE PLATE LIGHT	2	\$ 113.00	X nn	
8 LED TAIL LIGHT - LH/RH INNER	693.60 2	\$ LH-ut ✓ 1,734.00	RH X nn	
9 TAIL LIGHT TRIM - LH/RH INNER	23.36 2	\$ LH-de ✓ 60.00	RH X nn	
10 LED TAIL LIGHT - LH/RH OUTER	2	\$ LH- X nn 1,734.00	RH X nn	
11 TAIL LIGHT TRIM - LH/RH OUTER	2	\$ LH- X nn 60.00	RH X nn	
12 REAR REINFORCEMENT BEAM	451.60	\$ 565.00	? photo bt ✓	
13 REAR BUMPER BRACKET - LH/RH	19.84 2	\$ 26.00	? photo bt ✓	
14 REAR PARKING AID SENSOR - INNER/OUTER	1 ✓	\$ 193.04 484.00	nn ✓	193.04
15 REAR PARKING AID SEAL RING	4	\$ 10.88 14.00	rec ✓	
16 REAR BUMPER WIRING SET		\$ 510.00	? X nn	
17 REAR LID		\$ 2051.20 2,564.00	bt ✓	
18 REAR LID ATTACHMENT PARTS		\$ 291.00	X nn	
19 REAR LID HINGE - LH/RH	2	\$ 506.00	? X nn	
20 REAR LID FLAP GASKET		\$ 203.00	de X nn	
SUB TOTAL SPARE PARTS	:	\$ 11,309.00		



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCU 1680 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 REAR LID LOCK STRIKER		\$ 39.2	49.00	? bt ✓
22 REAR LID LOCK		\$	184.00	X } nn
23 REAR LID PUSH BUTTON		\$	172.00	X } nn
24 REAR LID COVER		\$	16.00	X } nn
25 PACKING ADHESIVE		\$ 14.40	18.00	nn ✓
26 AUDI EMBLEM		\$ 97.60	122.00	nn ✓
27 A3 INSCRIPTION		\$ 75.36	95.00	nn ✓
28 TFSI INSCRIPTION		\$ 75.36	95.00	nn ✓
29 REAR CROSS PANEL		\$ 284.40	356.00	bt - photo.
30 CROSS PANEL REINFORCEMENT		\$ 579.60	725.00	? photo bt ✓
31 CROSS PANEL CONNECTING PLATE - LH/RH	2	\$ 228	286.00	? photo bt ✓
32 REAR CROSS PANEL TRIM		\$ 122.40	153.00	de photo.
33 LUGGAGE COMPARTMENT FLOORING		\$	536.00	X
34 REAR LID TRIM PANEL		\$	303.00	X
35 REAR SILENCER		\$	712.00	? X
36 REAR SILENCER DUAL CLIP		\$	57.00	? X
37 EXHAUST SYSTEM RETAINER	2	\$	79.00	? X
38 EXHAUST TAIL PIPE TRIM - LH		\$	128.00	X
39 REAR BUMPER LOWER SPOILER CHROME TRIM			TBC	bt ✓
40 REAR NO PLATE	S/N	\$	60.00	X
SUB TOTAL SPARE PARTS		:	\$ 15,455.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCU 16801

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 STONE CHIP	S/N	\$	✓ 180.00 <i>nec</i>
42 CAVITY WAX	S/N	\$	✓ 140.00 <i>nec</i>
43 ACRYLIC SEALANT	S/N	\$	✓ 180.00 <i>nec</i>
44 SUNDRIES		\$ nec	300.00 ? 2.24
TOTAL SPARE PARTS	:	\$	27,564.00
TOTAL LABOUR CHARGES	:	\$	9,712.00
GRAND TOTAL	:	\$	37,276.00

ALL CHARGES ARE INCLUSIVE OF GST


LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 97495749
8/10/10 @ 350pm
Not Authorise
Ex: to be advise.

Resurvey before paint 08 days
Tanpin @ 11h and 10m

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT