



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction



14 Ang Mo Kio St.63, Block B (S) 569116

Tel : 6453 6279 / 6456 5410

Email : contact@kgcworkshop.com.sg

Not Authorized

1. B1. 11 Sep 8

3 days

Ang Wei Foong
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP 201104
Date 3/11/2020
No of Page : 1/2

Registration No : SLQ 4348P

Accident Date : 1-Nov-20

Our Ref : TP 201104

Model : Hyundai Tucson 1.6 GLS

Chassis No: KMHJ3812VJU530345

Engine Capacity 1.6

S/No	Qty	Items	Unit Price	Amount
1	1	Front upper bumper	\$ 625.00	\$ 625.00 X
2	1	Front lower bumper	\$ 385.00	\$ 385.00 X
3	1	Front bumper retainer RHS	\$ 15.00	\$ 15.00 X
4	1	Front bumper retainer LHS	\$ 15.00	\$ 15.00 X
5	1	Front radiator Grille with Chrome	\$ 985.00	\$ 985.00 ✓
6	1	Front lower radiator Grille	\$ 385.00	\$ 385.00 X
7	1	Front number plate garnish	\$ 20.00	\$ 20.00 X
8	1	Front bumper sponge	\$ 95.00	\$ 95.00 ✓
9	1	Front bumper reinforcement	\$ 885.00	\$ 885.00 X
			\$	3,410.00
			-20%	\$ 682.00
Total for spare parts			\$	2,728.00

Special Nett

1	1 set	Front Bumper Clips	\$ 50.00	\$ 50.00 X
2	1	No. Plate with Casing (front)	\$ 60.00	\$ 60.00 45.00
3	1	Front Bumper Lip/ Diffuser (body kit)	\$ 850.00	\$ 850.00 ✓
4	1	Body kit sealant	\$ 50.00	\$ 50.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total for SP \$ **1,010.00**

Sub-Total for Parts : \$ **3,738.00**

**KGC WORKSHOP PTE LTD**

Since 1967

Sincere • Secure • Satisfaction

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.		3000 700.00
2		To putty and spray paint on all accident damage parts and other accident affected areas		2200 700.00
3		To remove and install the bodykit		150.00 600
4		To check wiring system to facilitate repair and refit the same		100.00 150
5		Apply rust proofing on the adjacent panels		~50.00 X
			TOTAL AMOUNT :	<u>1,700.00</u>
			OVERALL COST :	<u>5,438.00</u>