

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKK 6394K
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2090885/WS

Date: 04 Nov 2020

Policy No: 5109307089-01

Veh Reg No: SKK6394K

Make/Model: TOYOTA TOYOTA
WISH CVT

Chassis No: JTDGG20W705003832

Engine No: 2ZR1273066

Reg. Date: 14/08/2013

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 02/11/2020

Not Authorised
U/Ry &
Assessing After Repair

Estimate Repair Cost to Vehicle No :SKK6394K

7-9 day

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	543.90	1 PC	543.90	✓
2 REAR BUMPER BRACKETS	55.50	2 PCS	111.00	✓
3 REAR BUMPER RH SIDE RETAINER	89.90	1 PC	89.90	✓
4 REAR BUMPER RH REFLECTOR	56.90	1 PC	56.90	X
5 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
6 REAR TAILGATE	1,275.90	1 PC	1,275.90	✓
7 TAILGATE LOGO	66.15	1 PC	66.15	✓
8 TAILGATE OUTER MOULDING	309.70	1 PC	309.70	✓
9 TAILGATE INNER LOCK	361.60	1 PC	361.60	✓
10 TAILGATE INNER RUBBER	302.60	1 PC	302.60	50% ✓
11 TAILGATE RH REFLECTOR	349.20	1 PC	349.20	✓
12 TAILGATE EMBLEM (VALVE)	39.90	1 PC	39.90	✓
13 TAILGATE INNER BOARD	382.10	1 PC	382.10	✓
14 REAR WINDSCREEN GLASS MOULDING	129.80	1 PC	129.80	✓
15 RH TAILLAMP	379.20	1 PC	379.20	✓
16 RH TAILLAMP LOWER RETAINER	49.90	1 PC	49.90	✓
17 REAR END PANEL OUTER	495.90	1 PC	495.90	✓
18 REAR END PANEL INNER	199.20	1 PC	199.20	✓
19 REAR END PANEL INNER TOP GARNISH	253.29	1 PC	253.29	✓
20 REAR END PANEL INNER TOP GARNISH CLIPS	3.50	4 PCS	14.00	✓
21 REAR FLOORBOARD TOP BOARD	569.20	1 PC	569.20	✓
22 REAR FLOORBOARD TOP BOARD SUPPORT	359.80	1 PC	359.80	✓
23 REAR RH FENDER INNER GARNISH	721.30	1 PC	721.30	✓
24 REAR RH FENDER	911.40	1 PC	911.40	✓
25 REAR RH FENDER GLASS MOULDING	369.90	1 PC	369.90	✓
			8,362.74	
	Less 25%		2,090.69	6,272.06
Special Net				
26 TAILGATE EMBLEM (ELEGANCE)	50.00	1 PC	50.00	✓
27 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
28 REAR RH FENDER GLASS GUM	20.00	1 PC	20.00	✓
29 REVERSE SENSOR	200.00	1 SET	200.00	✓
30 REAR NUMBER PLATE	45.00	1 PC	45.00	✓
31 REVERSE CAMERA	380.00	1 PC	380.00	✓
			735.00	735.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 02/11/2020

Estimate No: ES2090885/WS
Date: 04 Nov 2020
Policy No: 5109307089-01
Veh Reg No: SKK6394K
Make/Model: TOYOTA TOYOTA
WISH CVT
Chassis No: JTDGG20W705003832
Engine No: 2ZR1273066
Reg. Date: 14/08/2013

Estimate Repair Cost to Vehicle No :SKK6394K

Description	U/Price	Quantity	List Price	Amount
Labour			S\$	S\$
32 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
33 REMOVE & REFIX SEAT,CARPET,GARNISH, TOP ROOF LINING,ETC	120.00	1 LA	120.00	✓
34 REMOVE & REFIX REAR RH FENDER GLASS	80.00	1 LA	80.00	?
35 PANEL BEATING	1,800.00	1 LA	1,800.00	?
36 PUTTY & RESPRAY PAINT	1,300.00	1 LA	1,300.00	1200
37 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	50.00	1 PC	50.00	✓
38 RUSTPROOFING	100.00	1 LA	100.00	90
			3,570.00	3,570.00
			Total	S\$ 10,577.06
			Add GST @ 7%	740.39
			Total Amount Payable	S\$ 11,317.45

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE